

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	Re	ef:	CS3/LPC21005496/R1vf3e2	
	300 BEACH ROAD		Da	ate:	11/05/2021	
	#17-04/07 THE CO	NCOURSESINGAPORE 199555	_			
					LPC2	
1.						
	Insured Veh.	XD 4626M	Veh. Inspected		SJL 3449M	
	Policy No.	Z/21/VC10/109573	Coverage (\$)		0.00	
	Claim No.	21/21/21/VC10/024533	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		05/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ISIS 1.8LX A	c.c		1794	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	ZNM100057655	Colour		BLACK	
	Odometer	240903 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE		5 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE		5 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE		5 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE		5 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT O/S PORTION.				
5.	5. General Information					
	Accident Date	03/05/2021	Inspect Date / Tim	ne	05/05/2021 (02:24 PM)	
	Survey held at MAJESTY AUTOWORKS - 1 BUKIT BATOK CRESCENT #03-25					
	Repairer -					
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21005496/R1vf3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DEOD Ante Organizant OAE Lineared American

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$