

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005502/APA3Q2**Date:** 18/07/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJP1485A**Insured Vehicle No :** SMH3599Z

Date of Loss: 04/05/2021

Nature of Claim: TP

Claim No: 3034638952SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJP1485A**

Make & Model: HONDA STREAM, 1.8 X (A)

Engine No: R18A1797114

Reg. Date: 12/03/2009 (Man. Year: 2008)

Chassis No: RN61087629

Colour: White

Odometer: 166710 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,397.78	3,471.80	7,925.98	69.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,970.00	1,500.00	43.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,867.78	5,441.80	9,425.98	63.40
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	14,867.78	4,300.00	10,567.78	71.08
+ GST 7.00/7.00% (S\$)	1,040.74	301.00	739.74	71.08
Nett Amount (S\$)	15,908.52	4,601.00	11,307.52	71.08
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
Nett Liability (S\$)		5,161.00		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment: 05/05/2021

Date Inspected: 05/05/2021 Inspected At:

Cn Motors Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 BLK C #01-41
AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	698.60 FL	*698.60 FL
2	1		*REAR BUMPER LOWER BRACKET LH	Bent	70.40 FL	*70.40 FL
3	1		*REAR BUMPER LOWER BRACKET RH	Bent	70.40 FL	*70.40 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Necessary	43.80 FL	*43.80 FL
5	1		*REAR BUMPER SIDE RETAINER RH	Necessary	43.80 FL	*43.80 FL
6	1		*REAR BUMPER TOW COVER	Cracked	38.20 FL	*38.20 FL
7	1		*REAR TAILGATE (\$903.00) (50%)	Dented	1,398.50 F	*451.50 FN
8	1		*REAR TAILGATE SHOCK ABSORBER LH	Not Necessary	115.60 FL	*- FL
9	1		*REAR TAILGATE SHOCK ABSORBER RH	Not Necessary	115.60 FL	*- FL
10	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	347.60 FL	*- FL
11	1		*REAR TAILGATE INNER TRIM BOARD (\$285.00) (50%)	Cracked	456.30 F	*142.50 FN
12	1		*REAR TAILGATE TRIM BOARD HANDLER	Not Necessary	28.60 FL	*- FL
13	1		*REAR TAILGATE EMBLEM STREAM	Necessary	69.80 FL	*69.80 FL
14	1		*REAR TAILGATE LOGO	Not Necessary	70.80 FL	*- FL
15	1		*REAR TAILGATE LOCK (\$245.00) (50%)	Damaged	385.90 F	*122.50 FN
16	1		*REAR TAILGATE WEATHERSTRIPE	Cut	185.40 FL	*185.40 FL
17	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	589.00 FL	*- FL
18	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	228.30 FL	*125.00 FL
19	2		*REAR NUMBER PLATE LAMP	Not Necessary	338.40 FL	*- FL
20	1		*REAR TAILLAMP LH	Cracked	667.40 FL	*368.00 FL
21	1		*REAR TAILLAMP SIDE COVER LH	Not Necessary	25.00 FL	*- FL
22	1		*REAR TAILLAMP RH	Cracked	667.40 FL	*368.00 FL
23	1		*REAR TAILLAMP SIDE COVER RH	Not Necessary	25.00 FL	*- FL
24	1		*REAR END PANEL	Dented	625.00 FL	*425.00 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	267.80 FL	*182.00 FL
26	1		*REAR END PANEL CROSS MEMBER	Dented	343.60 FL	*343.60 FL
27	1		*REAR END PANEL CENTER GARNISH	Not Necessary	125.60 FL	*- FL
28	1		*REAR FLOOR TOP BOARD LH	Not Necessary	348.80 FL	*- FL
29	1		*REAR FLOOR TOP BOARD RH	Not Necessary	348.80 FL	*- FL
30	1		*REAR FLOOR PANEL	Repair	1,159.00 FL	*- FL
31	1		*REAR TOOLS COMPARTMENT LINING	Not Necessary	295.20 FL	*- FL
32	1		*REAR SPARE TYRE CARRIER	Not Necessary	347.00 FL	*- FL
33	1		*REAR SPARE TYRE CARRIER BRACKET	Not Necessary	321.00 FL	*- FL
34	1		*REAR SPARE TYRE BOLT	Not Necessary	74.00 FL	*- FL
35	1		*REAR EXHAUST MUFFLER	Not Necessary	965.00 FL	*- FL
36	1		*REAR FENDER INNER TRIM BOARD LH	Cracked	597.60 FL	*385.00 FL
37	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	597.60 FL	*- FL
38	1		*REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
39	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	65.00 FS	*10.00 FS
40	4		*REAR TAILLAMP CLIPS	Not Necessary	18.00 FS	*- FS
41	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
42	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*SEALANT	Not Necessary	100.00 FS	*- FS
44	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	13,568.80	4,298.50
- List Item Discount on L Items 20.00/20.00% (\$)	2,171.02	683.40
- Nett Item Discount on N Items 0.00/20.00% (\$)	0.00	143.30
Total Parts (\$)	11,397.78	3,471.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,200.00	800.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	800.00
3	WIRING CHECK	New	100.00	30.00
4	TO APPLY RUST PROOF ON ACCIDNET AREAS	New	150.00	60.00
5	TO APPLYTUFF COATING ON ACCIDENT AREAS	New	150.00	0.00
6	LABOUR FOR REMOVE & REFIX CUSHION /UPHOLSTERY /ROOF LINING TO FACILITATE THE REPAIR	New	300.00	80.00
7	LABOUR FOR RMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	300.00	80.00
8	TO CONDUCT WATER CHECK LEAKAGE	New	120.00	0.00
9	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
Gross Labour Cost (\$\$)			3,470.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >