

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21005504/KTF3E2

Date: 27/07/2021

REFERENCE

Insured/Claimant:	Efficient Power Services Pte Ltd	Policy No:	1900263843	
Date of Loss:	30/04/2021	Nature of Claim:	OD	Claim No: 2926263274SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2454J	Engine No:	1KD2842131
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFAT35Y00K212596
Reg. Date:	01/03/2019 (Man. Year: 2018)	Odometer:	62056 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8/8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,525.39	11,463.83	4,061.56	26.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,850.00	3,720.00	1,130.00	23.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,375.39	15,183.83	5,191.56	25.48
- Excess (\$\$)	600.00	600.00	0.00	0.00
Nett Amount (\$\$)	19,775.39	14,583.83	5,191.56	26.25

INSPECTION

Date of Assignment:	05/05/2021	
Date Inspected:	06/05/2021	Inspected At: Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	727.10 FL	*- FL
2	1		*FRONT BUMPER LH INNER BRACKET	Repair	292.10 FL	*- FL
3	1		*LH HEADLAMP	Cracked	1,145.10 FL	*1,145.10 FL
4	1		*FRONT GRILLE	Cracked	673.10 FL	*673.10 FL
5	1		*FRONT GRILLE CENTRE TOYOTA LOGO	Necessary	97.10 FL	*97.10 FL
6	1		*FRONT WIPER PANEL	Repair	258.10 FL	*- FL
7	1		*FRONT BODY PANEL	Bent	1,244.10 FL	*1,244.10 FL
8	1		*FRONT DYNA EMBLEM	Necessary	84.10 FL	*84.10 FL
9	1		*FRONT LH SIDE MIRROR GARNISH	Missing	192.30 FL	*192.30 FL
10	1		*FRONT LH SIDE MIRROR ASSY	Mtg Cracked	695.40 FL	*695.40 FL
11	1		*FRONT LH CORNER PANEL	Missing	258.20 FL	*258.20 FL
12	1		*FRONT WINDSCREEN MOULDING	Necessary	248.22 FL	*248.22 FL
13	1		*DASHBOARD ASSY	Cracked	980.60 FL	*980.60 FL
14	1		*AIR CON LOW PRESSURE HOUSE	Serviceable	509.00 FL	*- FL
15	1		*AIR CON EVAPORATOR UNIT	Housing Cracked	1,089.00 FL	*1,089.00 FL
16	1		*AIR CON BLOWER UNIT	Serviceable	1,135.10 FL	*- FL
17	1		*HEATER UNIT	Cracked	2,017.10 FL	*2,017.10 FL
18	1		*FRONT LH DOOR	Buckled	1,450.45 FL	*1,450.45 FL
19	1		*FRONT LH DOOR FRONT PILLAR OUTER	Bent	485.10 FL	*485.10 FL
20	1		*FRONT LH DOOR FRONT PILLAR INNER	Bent	405.00 FL	*405.00 FL
21	1		*FRONT LH DOOR REAR PILLAR	Repair	660.00 FL	*- FL
22	1		*FRONT LH DOOR INNER LOCK	Dented	509.00 FL	*509.00 FL
23	2		*FRONT LH DOOR HINGE (TOP & BOTTOM)	Bent	148.20 FL	*148.20 FL
24	1		*FRONT LH DOOR CHECKER	Serviceable	145.00 FL	*- FL
25	1		*FRONT LH WEATHERSTRIP	Serviceable	169.40 FL	*- FL
26	1		*FRONT LH DOOR INNER TRIM BOARD	Buckled	728.10 FL	*728.10 FL
27	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FL	*- FL
28	1		*FRONT LH DOOR GLASS	Shattered	408.10 FL	*408.10 FL
29	1		*FRONT LH DOOR GLASS OUTER MOULDING	Buckled	115.10 FL	*115.10 FL
30	1		*FRONT LH DOOR GLASS INNER MOULDING	Serviceable	110.12 FL	-
31	1		*FRONT LH DOOR GLASS REGULATOR	Distorted	395.00 FL	*395.00 FL
32	1		*FRONT LH DOOR GLASS REGULATOR MOTOR	Serviceable	509.00 FL	*- FL
33	1		*FRONT LH DOOR GLASS CHANNEL	Serviceable	145.10 FL	*- FL
34	1		*FRONT CABIN REAR RAILING	Repair	685.40 FL	-
35	1		*FRONT LH STEP PANEL	Bent	435.10 FL	*435.10 FL
36	1		*FRONT LH STEP GARNISH	Cracked	218.10 FL	*218.10 FL
37	1		*FRONT LH DOOR LOWER COMPANY BLACK STICKER	Necessary	40.00 FS	*25.00 FS
38	1		*AIR-CON CONDENSER ASSY (Supplementary)	Bent	950.30 FL	*950.30 FL
39	1		*LH PANEL, INSTRUMENT, LWR (Supplementary)	Mtg Cracked	279.90 FL	*279.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,687.19	15,276.77
- List Item Discount on L Items 25.00/25.00% (\$)	5,161.80	3,812.94
Total Parts (\$)	15,525.39	11,463.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	120.00	60.00
2	LABOUR CHARGES FOR REMOVE / REFIT, CUTTING / WELDING AND REPLACEMENT OF DAMAGES	New	2,000.00	1,600.00
3	TO PUTTY AND SPRAY PAINTINGS CHARGES	New	2,000.00	1,600.00
4	TO REMOVE, REFIT FRONT WINDSCREEN GLASS	New	140.00	60.00
5	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
6	TO REMOVE, REFIT DASHBOARD ASSY	New	250.00	220.00
7	TO REMOVE, REFIT AIR CON BLOWER / EVAPORATOR UNIT, INCLUDING REFILL AIR CON GAS	New	140.00	100.00
8	TO REMOVE, REFIT BRAKE BOOSTER PUMP, BRAKE HOSES / PIPINGS, CLUTCH HOSE AND BLEED SYSTEMS	New	80.00	0.00
9	TO REMOVE, REFIT FRONT LH DOOR FITTINGS	New	80.00	60.00
Gross Labour Cost (\$\$)			4,850.00	3,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >