

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21005509/KGS3Q2
Date: 27/09/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SLT3693H	Insured Vehicle No :	GBH8075R
Date of Loss:	03/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001954

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3693H	Engine No:	10XTA40763410
Make & Model:	PEUGEOT 3008, 1.6 (A)	Chassis No:	VF3MRHNYWHS209706
Reg. Date:	27/10/2017 (Man. Year: 2017)	Odometer:	48833 km
Colour:	Metallic Blue		
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Scorpion 9 mm	Rear Left Side:	Scorpion 9 mm
Front Right Side:	Scorpion 9 mm	Rear Right Side:	Scorpion 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,209.20	3,547.80	2,661.40	42.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,790.00	1,070.00	37.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,069.20	5,337.80	3,731.40	41.14
Approved Total (Overridden) (S\$)		4,250.00		

Nett Amount (S\$)	9,069.20	4,250.00	4,819.20	53.14
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,557.00		

INSPECTION

Date of Assignment: 05/05/2021

Date Inspected: 06/05/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Loh Heng (HQ)
176 Sin Ming Drive, #03-08 Sin Ming Auto Care
Singapore 575721**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2021)
Parts: 144	PEUGEOT 3008 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLT3693H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LEFT FENDER	Bent	1,690.00 FL	*1,316.00 FL
2	1		*REAR LEFT FENDER ARK TRIM	Distorted	357.00 FL	*357.00 FL
3	1		*REAR LEFT WHEEL COWLING	Serviceable	298.00 FL	*- FL
4	1		*REAR BUMPER	Repair	1,320.00 FL	*- FL
5	1		*REAR BUMPER BRACKET	Serviceable	192.00 FL	*- FL
6	1		*REAR WHEEL HUB	Bent	549.00 FL	*549.00 FL
7	1		*REAR LOWER SUSPENSION CROSS MEMBER	Bent	1,880.00 FL	*1,720.00 FL
8	1		*REAR LEFT WHEEL RIM	Not Necessary	250.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,536.00	3,942.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	326.80	394.20
Total Parts (\$\$)	6,209.20	3,547.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DO 4 WHEEL ALIGNMENT	New	120.00	60.00
2	REMOVE QUARTOR GLASS AND REFIX	New	60.00	60.00
3	TO DISMANTLE CUT OUT REAR FENDER TO PANEL BEAT ,RESHAPE STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,400.00	700.00
4	TO REMOVE AND REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIR	New	180.00	100.00
5	TO RUSTPROOF ALL AFFECTED PORTION AFTER REPAIR	New	100.00	30.00
6	REMOVE AND REFIX SUSPENSION	New	200.00	180.00
7	SUPPLY SPRAY PAINT MATERIAL AND SPRAY PAINT ON NECESSARY ITEMS AND THE AFFECTED AREA	New	800.00	660.00
			Gross Labour Cost (S\$)	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >