

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	F	Ref:	CS3/LPC21005512/R1tf3e2	
	300 BEACH ROAD		Г	Date:	10/06/2021	
	#17-04/07 THE CO	NCOURSESINGAPORE 199555		<b>3</b>	L DO0	
4		Dallar Bardania		Code:		
1.	Policy Particulars :- (THIRD			,		
	Insured Veh.	YN 1475L	Veh. Inspected		JJG 9813	
	Policy No.	00/04/04/04000	Coverage (\$)		0.00	
	Claim No.	20/21/21/VC05/024534	Excess (\$)		0.00	
	Assign From	ONG LI LI	Assign Date		05/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA INNOVA	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	PN111NV4008602142	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/50Z R17	APLUS		6 mm	
	L/H Front Tyre	225/50Z R17	APLUS		6 mm	
	R/H Rear Tyre	225/50Z R17	APLUS		6 mm	
	L/H Rear Tyre	225/50Z R17	APLUS		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	04/05/2021	Inspect Date / Ti	ime	07/05/2021 ( 11:11 AM )	
	Survey held at	ENG SOON PAINTING SVC				
		BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21005512/R1tf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser