

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005515/DQF3N2**Date:** 18/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00121502000

**Claimant Vehicle
No :** SLP4227K**Insured
Vehicle No :** GBK8592Z

Date of Loss: 01/05/2021

Nature of Claim: TP

Claim
No: SNM21D202578/C02/LOWCT**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLP4227K**

Make & Model: TOYOTA VIOS, 1.5 E CVT (A)

Engine No: 2NRX147099

Reg. Date: 05/06/2017 (Man. Year: 2017)

Chassis No: MHFB29F3602010100

Colour: Grey

Odometer: 53393 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size: 195/60 R16

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,146.41	2,602.12	9,544.29	78.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,240.00	1,410.00	3,830.00	73.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,386.41	4,012.12	13,374.29	76.92
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	17,386.41	3,200.00	14,186.41	81.59
+ GST 7.00/7.00% (\$\$)	1,217.05	224.00	993.05	81.59
Nett Amount (\$\$)	18,603.46	3,424.00	15,179.46	81.59

INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 05/05/2021 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2021)
Parts:	143	TOYOTA VIOS 1.5 E CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP4227K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,258.70 FL	*821.61 FL
2	1		*BOOTLID VIOS EMBLEM	Necessary	64.20 FL	*64.20 FL
3	1		*BOOTLID E EMBLEM	Necessary	54.37 FL	*54.37 FL
4	1		*BOOTLID TOYOTA LOGO	Necessary	70.20 FL	*70.20 FL
5	1		*BOOTLID NO PLATE TOP GARNISH	Mounting Broken	278.20 FL	*278.20 FL
6	2		*BOOTLID NO PLATE LAMP L+R	Not Necessary	113.96 FL	*- FL
7	1		*BOOTLID LOCK	Serviceable	289.95 FL	*- FL
8	1		*BOOTLID STRIKER LOCK	Not Necessary	82.94 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Necessary	175.35 FL	*175.35 FL
10	1		*REAR BUMPER	Distorted/Dented	807.50 FL	*581.50 FL
11	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	184.66 FL	*- FL
12	1		*REAR BUMPER REFLECTOR L+R	N/s Mounting Broken	165.62 FL	*82.81 FL
13	1		*TAIL LAMP L+R	N/s Mounting Broken	1,555.24 FL	*376.00 FL
			O/s Not Necessary			
14	2		*TAIL LAMP PANEL L+R	Not Necessary	610.00 FL	*- FL
15	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	278.04 FL	*- FL
16	1		*REAR REINFORCEMENT BAR	Bent	660.00 FL	*374.50 FL
17	1		*REAR END PANEL	Repair	671.89 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Mounting Broken	230.76 FL	*230.76 FL
19	2		*REAR FENDER INNER TRIM L+R	Not Necessary	648.40 FL	*- FL
20	2		*REAR FENDER L+R	Not Necessary	2,409.70 FL	*- FL
21	1		*SPARE WHEEL PANEL	Not Necessary	837.85 FL	*- FL
22	2		*SPARE WHEEL QUARTER PANEL L+R	Not Necessary	598.60 FL	*- FL
23	1		*SPARE WHEEL PANEL STYROFOAM	Not Necessary	214.00 FL	*- FL
24	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	314.38 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	875.60 FL	*- FL
26	1		*REAR EXHAUST MOUNTING	Not Necessary	80.00 FL	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	249.50 FL	*- FL
28	1		*REAR KEYLESS SENSOR	Not Necessary	295.60 FL	*- FL
29	1		*REAR NUMBER PLATE & CASING	Not Necessary	100.00 FS	*- FS
30	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
31	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS
32	1		*REAR END PANEL SEALANT	Not Necessary	70.00 FS	*- FS
33	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*20.00 FS
34	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
35	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
36	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
37	1		*REAR BOOTLID CENTER MOULDING CLIPS	Necessary	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,665.21** **3,379.50**
- List Item Discount on L Items 25.00/25.00% (\$\$) **3,518.80** **777.38**

Total Parts (\$\$) **12,146.41** **2,602.12**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO RNR REAR EXHAUST TO FACILITATE REPAIRS	New	120.00	0.00
5	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	120.00	60.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	New	300.00	40.00
8	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	200.00	0.00
Gross Labour Cost (\$\$)			5,240.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >