

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005517/T1GA3Q2
Date: 13/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700049266-03
Claimant Vehicle No :	SH7012C	Insured Vehicle No :	EH1118L
Date of Loss:	04/05/2021	Nature of Claim:	TP
		Claim No:	8252694512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7012C		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS042641
Reg. Date:	25/05/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU103556797
Colour:	Blue	Odometer:	462387 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,559.19	1,634.21	924.98	36.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	1,165.00	455.00	28.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,179.19	2,799.21	1,379.98	33.02
Approved Total (Overridden) (S\$)		2,250.00		

(S\$)	4,179.19	2,250.00	1,929.19	46.16
+ GST 7.00/7.00% (S\$)	292.54	157.50	135.04	46.16
Nett Amount (S\$)	4,471.73	2,407.50	2,064.23	46.16
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$125.40/day) (S\$)		313.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,848.00		
Global Sum Settlement (S\$)		2,800.00		

INSPECTION

Date of Assignment: 05/05/2021

Date Inspected: 05/05/2021

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	499.90 FL	*499.90 FL
2	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FENDER SUB-ASSY ,FRONT LH	Repair	945.30 FL	*- FL
4	1		*FRONT FENDER HYBRID EMBLEM -LH	Necessary	86.50 FL	*86.50 FL
5	1		*FRONT SPORT RIM LH	Cut	1,570.55 FL	*1,570.55 FL
6	1		*FRONT WESKLAKE TYRE LH	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,340.25	2,178.95
- List Item Discount on L Items 25.00/25.00% (\$\$)	781.06	544.74
Total Parts (\$\$)	2,559.19	1,634.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	525.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	WHEEL ALIGNMENT	New	120.00	80.00
4	TUFF KOTE	New	40.00	0.00
5	TOWING FEE	New	60.00	60.00
Gross Labour Cost (S\$)			1,620.00	1,165.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >