

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21005520/Evce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 20/05/2021 SINGAPORE 068811 ATTN: TAN JUN HONG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHC 7075C** FBF 3108Z Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S1M033OR Excess (\$) 0.00 TAN JUN HONG Assign From **Assign Date** 05/05/2021 **Vehicle Particulars & Condition** 2. YAMAHA T135 c.c 135 Make & Model HIDDEN 2011 Engine No. Year of Reg. 5YP303236 YELLOW Chassis No. Colour Odometer 27988 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 60/70-17 DUNLOP 5 mm L/H Front Tyre mm 70/80-17 DUNLOP R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 07/01/2021 06/05/2021 (04:00 PM) **Accident Date** Inspect Date / Time PROJECT 8 MOTORWORKS Survey held at 6 DEFU LANE 10 #01-554 SINGAPORE 539187 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/ASM21005520/Evce2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$1,500

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

3 Working Days