

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21005524/T1TF3E2

Date: 09/06/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001301035		
Claimant Vehicle No :	SBS8183D	Insured Vehicle No :	SLL49E		
Date of Loss:	01/05/2021	Nature of Claim:	TP	Claim No:	256795

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS8183D	Engine No:	6385924
Make & Model:	SCANIA KUB4X2, 8.9 ABS TURBO 2WD (A)	Chassis No:	YS2K4X20001860385
Reg. Date:	13/05/2008 (Man. Year: 2008)	Odometer:	943034 km
Colour:	Multi-colour		
Engine Capacity:	8867 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,378.00	1,378.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	1,100.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,478.00	2,478.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	173.46	173.46	0.00	0.00
Nett Amount (S\$)	2,651.46	2,651.46	0.00	0.00

INSPECTION

Date of Assignment:	06/05/2021		
Date Inspected:	06/05/2021	Inspected At:	Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4 Singapore 489946
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Jun 2021)	
Parts:	N/A	SCANIA KUB4X2 8.9 ABS TURBO 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS8183D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER.REAR.F/G	Cracked	170.00 F	*170.00 F
2	1		*LED TAIL/STOP LAMP	Cracked	92.00 F	*92.00 F
3	1		*REFLEX REFLECTOR	Cracked	1.00 F	*1.00 F
4	1		*LED REVERSE LAMP	Cracked	101.00 F	*101.00 F
5	1		*RR LAMP PANEL;N/S	Cracked	138.00 F	*138.00 F
6	2		*DOOR RETAINER;PANEL;METAL	Bent	64.00 F	*64.00 F
7	1		*RADIATOR GRILL JL~KL;SIDE PANEL ASSY	Bent	612.00 F	*612.00 F
8	1		*ADVERTISEMENT	Necessary	200.00 FS	*200.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					1,378.00	1,378.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR	New	1,100.00	1,100.00
Gross Labour Cost (\$\$)			1,100.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >