

Case Details

Case Reference Number : TAX/05/21/2008
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4741H

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-14799-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : ERGO Insurance Pte Ltd
Accident Date and Time : 04/05/2021 03:50 AM
Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents : 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair ✓ X R
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0	Not Give ✓ X NM
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give ✓ X NM
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give ✓ X NM
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give ✓ X NM
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give ✓ X NM
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give ✓ X NM
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give ✓ X NM
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give ✓ X NM
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair ✓ X R

Total Spare Part Cost 6,418.91

Lump Sum Discount (%) 20.00

Final Spare Part Cost 5,135.13

Surveyor Total 1,228.56

Lump Sum Dis (%) 20

Final Sur Total 982.85

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.973	Replace	✓ MC
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	1	128.778	Replace	✓ TN
One Time Key In	Main			FENDER LINER PAD, FR WHEEL, RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	✓ X NM
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give	✓ X NM
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ X NM
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Not Give	✓ X NM
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	0	0	Not Give	✓ X NM
One Time Key In	Main			MIRROR ASSY,RH	1	1,307.10	1,307.10	25.00	980.32	Replace	1	980.373	Replace	✓ BR
One Time Key In	Main			MIRROR GLASS RH	1	212.80	212.80	25.00	159.60	Replace	0	0	Not Give	✓ X NM
One Time Key In	Main			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	✓ X NM
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	1	80.55	Replace	✓ BR

Total Spare Part Cost	6,418.91	Surveyor Total	1,228.56
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	5,135.13	Final Sur Total	982.85

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	507.00	200	✓
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,296.00	450.00	

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	0	
4	Main	RESPRAY MIRROR COVER RH	180.00	50	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
Total:			1,296.00	450.00	✓

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	30	OK ✓
2	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	X N/A
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	X N/A
4	Main	TO REPLACE SUNDRY PARTS	100.00	10	OK ✓
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	OK ✓
6	Main	TO WASH AND VACUUM	60.00	0	X N/A
Total:			600.00	60.00	✓

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,135.13	982.85
Total Labour Cost	507.00	200.00
Total Spray Painting	1,296.00	450.00
Other	600.00	60.00
Overall Total	7,538.13 \$10614.84	1,938.56
Lump Sum Repair Option	☐	☒
Lump Sum Total	7,550.00	1,950.00
Surveyor Approved Amount		1,950.00
No of Repair Days*	5	3

Remarks

Estimator Assessment(\$)


Surveyor Assessment(\$)

LUMPSUM REPAIR, TAKE AFTER SPRAY

Surveyor Name

Signature

STEVE CHEN



Save

Clear

Survey Date

06/05/2021

Steve (LKK) Mr An
L/S
6/5/21, 1.00pm
3 days
By AL Sy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: