



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 2681S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED / CUT	638.00	638.00
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	45.00	-
1	FRONT LH FENDER INNER SHIELD	CRACKED	150.00	150.00
1	FRONT LH LOWER ARM	DISTORTED	243.00	243.00
1	FRONT LH SHOCK ABSORBER	BENT	259.00	259.00
1	FRONT KNUCKLE ARM BEARING LH	NECESSARY	166.00	166.00
1	FRONT LH KNUCKLE ARM	BENT	305.00	305.00
	LESS 20% DISCOUNT		-	-352.20
			1,806.00	1,408.80
<u>SPECIAL NETT ITEMS</u>				
1	TYRE (SN)	SERVICEABLE	380.00	-
1	SPORT RIM (SN)	DENTED	480.00	480.00
10	FENDER INNER SHIELD CLIP @\$2.00 (SN)	NECESSARY	20.00	20.00
			880.00	500.00
<u>LABOUR</u>				
	REMOVE & FIX BACK FRONT BUMPER AND INNER SHIELD.		250.00	200.00
	REMOVE & FIX BACK UNDERCARRIAGE.		450.00	180.00
	WHEEL ALIGNMENT.		180.00	60.00
	SPRAY PAINTING.		300.00	200.00
			1,180.00	640.00
GRAND TOTAL			3,866.00	2,548.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/AGI21005530/Kuf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.