

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21005533/UQF3E2

**Date:** 29/06/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00003312000  
Claimant Vehicle No: SMW587Z Insured Vehicle No: PC7897C  
Date of Loss: 05/05/2021 Nature of Claim: TP Claim No: SNM21D202607/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMW587Z  
Make & Model: HONDA JAZZ, 1.5 (A) Engine No: L15A71004052  
Reg. Date: 25/11/2010 (Man. Year: 2008) Chassis No: JHMGE88509S203286  
Colour: White Odometer: 100196 km  
Engine Capacity: 1497 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,208.00	3,750.00	458.00	10.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,503.02	1,448.42	54.60	3.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,711.02</b>	<b>5,198.42</b>	<b>512.60</b>	<b>8.98</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,450.00</b>		
<b>(S\$)</b>	5,711.02	4,450.00	1,261.02	22.08
<b>+ GST 7.00/7.00% (S\$)</b>	399.77	311.50	88.27	22.08
<b>Nett Amount (S\$)</b>	<b>6,110.79</b>	<b>4,761.50</b>	<b>1,349.29</b>	<b>22.08</b>

### INSPECTION

Date of Assignment: 05/05/2021 Present Location: Jin Auto Services Pte Ltd (Defu)  
Date Inspected: 06/05/2021 Inspected At: Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195  
Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2021)
Parts:	144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW587Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*parts		4,208.00 F	*3,750.00 F
Total Parts (\$\$)						3,750.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	labour	New	907.20	852.60
2	spray paint	New	595.82	595.82
<b>Gross Labour Cost (S\$)</b>			<b>1,503.02</b>	<b>1,448.42</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >