

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI21005535/T1VF3E2**Date:** 07/06/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000509
<b>Claimant Vehicle No :</b>	SHA2808Z	<b>Insured Vehicle No :</b>	SML4365D
Date of Loss:	05/05/2021	Nature of Claim:	TP
		Claim No:	M2102224

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA2808Z</b>		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU412282
Reg. Date:	06/08/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU190836
Colour:	Blue	Odometer:	104819 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,328.12	976.12	352.00	26.50
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	780.00	630.00	150.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,119.12</b>	<b>1,617.12</b>	<b>502.00</b>	<b>23.69</b>
<b>+ GST 7.00/7.00% (S\$)</b>	148.34	113.20	35.14	23.69
<b>Nett Amount (S\$)</b>	<b>2,267.46</b>	<b>1,730.32</b>	<b>537.14</b>	<b>23.69</b>

INSPECTION

Date of Assignment:	05/05/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	05/05/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 06 Jun 2021)

**Parts:** 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHA2808Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER ASSY	Deformed	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER MOULDING CENTRE	Cracked	451.25 FL	-	*451.25 FL
3	10		*REAR BUMPER CLIPS	Necessary	220.00 FL	-	*22.00 FL
4	1		*ANTENNA ASSY - SMARTK	Not Necessary	40.50 FL	-	*- FL
5	1		*REAR FOG LAMP	Not Necessary	201.50 FL	-	*- FL
6	1		*REAR NUMBER PLATE W/CASING	Cracked	50.00 F	-	*50.00 F

#### Supplementary #1

7	1		*REVERSE SENSOR	Not Working	180.00 F	-	*180.00 F
---	---	--	-----------------	-------------	----------	---	-----------

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,602.65</b>	<b>1,162.65</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	274.53	186.53
<b>Total Parts (\$\$)</b>	<b>1,328.12</b>	<b>976.12</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			780.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >