



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 7175B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	CRACKED	900.00	688.00
2	REAR BUMPER RETAINER	SERVICEABLE	180.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,530.00	-
1	REAR WINDSCREEN MOULDING	SERVICEABLE	190.00	-
1	REAR DOOR PANEL RH	TO REPAIR SEE LABOUR	1,430.00	-
1	FRONT DOOR PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-423.00	-68.80
			3,807.00	619.20
1	REAR DOOR PROTECTOR RH (SN)	NECESSARY	210.00	74.00
1	FRONT DOOR PROTECTOR RH (SN)	NECESSARY	210.00	74.00
	LESS 10% DISCOUNT		-42.00	-
			378.00	148.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	RIM (SN)	GRAZED	1,200.00	300.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	JOINT SEALANT (SN)	SERVICEABLE	150.00	-
1	WINDSCREEN SEALANT (SN)	SERVICEABLE	150.00	-
			1,560.00	330.00
	<b><u>LABOUR</u></b>			
	CHECK REAR WIRING AND LIGHTNING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		200.00	60.00
	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT.		180.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TRANSFER PARTS, ATTACHMENT FROM OLD REAR DOOR TO NEW.	NOT NECESSARY	250.00	-
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH, REAR DOOR PANEL RH AND FRONT DOOR PANEL RH.		1,800.00	400.00

Report Ref No. CS3/SMO20014748/GUqf3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON AFFECTED AREAS.	NOT NECESSARY	1,600.00	800.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	-
			4,390.00	1,350.00
GRAND TOTAL			10,135.00	2,447.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CS3/SMO20014748/GUqf3e2-1

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.