

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/CTI21005551/BQF3Q2

Date:

14/06/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00115142000
Claimant Vehicle No :	SMS7625Y	Insured Vehicle No :	GBK7443C
Date of Loss:	04/05/2021	Nature of Claim:	TP
		Claim No:	SNM21D202601/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS7625Y		
Make & Model:	MAZDA 6, 2.0 SEDAN STANDARD 2WD (A)	Engine No:	PE21282768
Reg. Date:	12/03/2020 (Man. Year: 2019)	Chassis No:	JM6GL1072K0318047
Colour:	Grey	Odometer:	21191 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,856.80	4,452.26	4,404.54	49.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	1,890.00	2,180.00	53.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,926.80	6,342.26	6,584.54	50.94
Approved Total (Overridden) (S\$)		5,050.00		

(S\$)	12,926.80	5,050.00	7,876.80	60.93
+ GST 7.00/7.00% (S\$)	904.88	353.50	551.38	60.93
Nett Amount (S\$)	13,831.68	5,403.50	8,428.18	60.93

INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 06/05/2021

Inspected At:

Ah Chang Motor Service Centre (HQ)
 10 ANG MO KIO INDUSTRIAL PARK 2A, ANG MO KIO POINT #03-16
 Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2021)
Parts:	143	MAZDA 6 2.0 SEDAN STANDARD 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS7625Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Broken	1,682.00 FL	*1,099.00 FL
2	1		*REAR BUMPER LEFT BRACKET	No such part	64.00 FL	*- FL
3	1		*REAR BUMPER LEFT SIDE RETAINER	Necessary	68.00 FL	*30.00 FL
4	1		*REAR LEFT FENDER	Dented	1,462.00 FL	*1,120.50 FL
5	1		*REAR LEFT FENDER INNER COWLING	Broken	288.00 FL	*184.00 FL
6	1		*REAR LEFT SHOCK ABSORBER	Bent	486.00 FL	*195.20 FL
7	1		*REAR LEFT KNUCKLE ARM	Not Damaged	682.00 FL	*- FL
8	1		*REAR LEFT LOWER ARM	Bent	423.00 FL	*308.33 FL
9	1		*REAR LEFT TRAILING LINK	Bent	353.00 FL	*353.00 FL
10	1		*REAR LEFT TRAILING ARM	Bent	295.00 FL	*163.80 FL
11	1		*REAR LEFT WHEEL HUB WITH BEARING	Jammed	256.00 FL	*256.00 FL
12	1		*REAR LEFT SUSPENSION SPRING	Not Damaged	325.00 FL	*- FL
13	1		*REAR LEFT LOWER CARRIER	Bent	438.00 FL	*308.00 FL
14	1		*REAR LEFT BALL JOINT	Not Damaged	183.00 FL	*- FL
15	1		*REAR LEFT BRAKE DISC	Not Damaged	235.00 FL	*- FL
16	1		*REAR LEFT TAILLAMP	Broken	867.00 FL	*751.00 FL
17	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	288.00 FL	*- FL
18	1		*REAR LEFT QUARTER CHROME PANEL	Not Necessary	389.00 FL	*- FL
19	1		*REAR LEFT FUEL TANK COVER	Not Damaged	128.00 FL	*- FL
20	1		*BUMPER LH REAR INNER GARNISH	Broken	184.00 FL	*184.00 FL
21	10		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
22	1		*REAR LEFT WHEEL RIM	Bent	880.00 FS	*400.00 FS
23	1		*REAR LEFT TYRE	Not Damaged	400.00 FS	*- FS
24	1		*REAR LEFT FENDER SEALANT	Necessary	100.00 FS	*40.00 FS
25	1		*REAR LEFT FENDER INNER COWLING CLIPS (6 PCS)	Necessary	40.00 FS	*20.00 FS
26	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	10,676.00
					- List Item Discount on L Items 20.00/20.00% (\$)	1,819.20
					Total Parts (\$)	8,856.80

5,442.83

990.57

4,452.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR AND REAR LEFT AFFECTED AREAS AND REPLACE REAR AND REAR LEFT DAMAGED PARTS	New	1,400.00	700.00
2	TO PUTTY AND SPRAY PAINTING REAR AND REAR LEFT PORTION	New	1,400.00	700.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	0.00
4	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	180.00	80.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	60.00
6	TO APPLY ANTI RUST PROOFING TO REAR AND REAR LEFT AFFECTED AREA	New	140.00	60.00
7	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	0.00
8	TO REMOVE AND INSTALL REAR LEFT UNDERCARRIAGE PARTS	New	350.00	200.00
9	TO BALANCER REAR LEFT WHEEL	New	50.00	30.00
10	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
11	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (S\$)			4,070.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >