

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21005555/KVF3N2**Date:** 24/08/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00165392000

**Claimant Vehicle No :** SMS8048G **Insured Vehicle No :** SMR7566P

Date of Loss: 02/05/2021 Nature of Claim: TP Claim No: SNM21D202573/C2/IRENEE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS8048G**

Make & Model: TOYOTA COROLLA, 1.8 Sport Ascent CVT (A) Engine No: 2ZR2C24734

Reg. Date: 16/03/2020 (Man. Year: 2018) Chassis No: JTNK93BE603003424

Colour: Metallic Pearl White Odometer: 49893 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,248.75	5,009.85	6,238.90	55.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	720.00	1,830.00	71.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,798.75</b>	<b>5,729.85</b>	<b>8,068.90</b>	<b>58.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>(S\$)</b>	13,798.75	4,200.00	9,598.75	69.56
<b>+ GST 7.00/7.00% (S\$)</b>	965.91	294.00	671.91	69.56
<b>Nett Amount (S\$)</b>	<b>14,764.66</b>	<b>4,494.00</b>	<b>10,270.66</b>	<b>69.56</b>

INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 05/05/2021 Inspected At: Fulco Autocare Pte Ltd (HQ)  
176 SIN MING DRIVE #03-02 SIN MING  
AUTOCARE  
Singapore 575721

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2021)**Parts:** 143 TOYOTA COROLLA 1.8 Sport Ascent CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMS8048G)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,783.00 FL	*- FL
2	1		*BONNET LOCK	Repair	339.00 FL	*- FL
3	1		*BONNET BOTTOM LOCK ASSY	Repair	158.00 FL	*- FL
4	1		*SUPPORT PANEL	Repair	835.00 FL	*- FL
5	1		*SUPPORT PANEL TOP GARNISH	Serviceable	298.00 FL	*- FL
6	2		*HEADLAMP SUPPORT	Repair	334.00 FL	*- FL
7	2		*HEADLAMP	Mtg Cracked	5,792.00 FL	*5,792.00 FL
8	2		*HEADLAMP LOWER BRACKET	Repair	156.00 FL	*- FL
9	1		*FRONT BUMPER	Buckled/Mtg Cracked	1,586.00 FL	*371.30 FL
10	2		*FRONT BUMPER SIDE CHROME MOULDING	Serviceable	750.00 FL	*- FL
11	1		*RADIATOR GRILLE TOYOTA LOGO	Necessary	116.00 FL	*116.00 FL
12	2		*FRONT BUMPER SIDE RETAINER	Serviceable	176.00 FL	*- FL
13	2		*FRONT BUMPER BRACKET	Repair	108.00 FL	*- FL
14	1		*RADIATOR GRILLE	Cracked	657.00 FL	*312.50 FL
15	1		*FRONT BUMPER SPONGE	Serviceable	278.00 FL	*- FL
16	1		*FRONT BUMPER LOWER GRILLE	Serviceable	594.00 FL	*- FL
17	1		*FRONT BUMPER REINFORCEMENT	Repair	689.00 FL	*- FL
18	12		*BONNET INSULATOR CLIPS	Not Necessary	66.00 FS	*- FS
19	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
20	12		*FRONT BUMPER CLIPS	Necessary	66.00 FS	*66.00 FS
21	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,911.00</b>	<b>6,657.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	3,662.25	1,647.95
<b>Total Parts (\$\$)</b>	<b>11,248.75</b>	<b>5,009.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	300.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS.RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,200.00	400.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>2,550.00</b>
				<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >