

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG21005556/KGS3Q2  
**Date:** 06/07/2021

### REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100289931   |
| <b>Claimant Vehicle No :</b> | SJZ1923A                             | <b>Insured Vehicle No :</b> | SJN9120K     |
| Date of Loss:                | 02/05/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 4128271308SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJZ1923A</b>                   |             |                   |
| Make & Model:               | VOLVO XC40, 2.0 T4 MOMENTUM (A)   | Engine No:  | B4204T472929820   |
| Reg. Date:                  | 25/02/2019 (Man. Year: 2018)      | Chassis No: | YV1XZACADK2113583 |
| Colour:                     | White                             | Odometer:   | 49873 km          |
| Engine Capacity:            | 1969 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 235/50 R19   | Rear Tyre Size:  | 235/50 R19   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 3,708.81          | 828.90            | 2,879.91          | 77.65         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,160.00          | 485.00            | 675.00            | 58.19         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>4,868.81</b>   | <b>1,313.90</b>   | <b>3,554.91</b>   | <b>73.01</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>1,050.00</b>   |                   |               |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                        | <b>4,868.81</b> | <b>1,050.00</b> | <b>3,818.81</b> | <b>78.43</b> |
| <b>+ Car Rental (1.0 x S\$120.00/day) (S\$)</b> |                 | 120.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 7.45            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>1,177.45</b> |                 |              |

INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 07/05/2021

Estimated Period of Repair: 1.0 days

Inspected At:

Lim Yew Boo Spray Paint Co (HQ)  
 Blk 10 Sin Ming Industrial Estate, #01-10  
 Singapore 575645

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition        | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------|------------------|-------------|------------|
| 1   | 1   |          | *FRONT BUMPER                    | Serviceable      | 2,100.00 FL | *- FL      |
| 2   | 1   |          | *FRONT BUMPER FOG LAMP COVER /RH | Serviceable      | 151.00 FL   | *- FL      |
| 3   | 1   |          | *FRONT BUMPER GRILLE CENTRE      | Serviceable      | 208.90 FL   | *- FL      |
| 4   | 1   |          | *FRONT BUMPER SPOILER            | Dented / Buckled | 921.00 FL   | *921.00 FL |
| 5   | 1   |          | *FRONT BUMPER PROTECTION PLATE   | Serviceable      | 410.00 FL   | *- FL      |
| 6   | 1   |          | *FRONT BUMPER TOWING COVER /RH   | Serviceable      | 80.00 FL    | *- FL      |
| 7   | 1   |          | *FRONT BUMPER SENSOR             | Not Necessary    | 225.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |               |
|----------------------------------------------------------|-----------------|---------------|
| <b>Sub Total (\$)</b>                                    | <b>4,095.90</b> | <b>921.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 387.09          | 92.10         |
| <b>Total Parts (\$)</b>                                  | <b>3,708.81</b> | <b>828.90</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                          | Lab.Type | Repairer's      | Amount        |
|---------------------------------|------------------------------------------------------------------------------------------------------|----------|-----------------|---------------|
| <u>Labour Items</u>             |                                                                                                      |          |                 |               |
| 1                               | LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS                                                | New      | 80.00           | 50.00         |
| 2                               | TO CHECK FRT LEFT HEADLAMP ,FOGLAMP & WIRING FUNCTION                                                | New      | 80.00           | 15.00         |
| 3                               | TO REPAIR ,ALIGN ON FRT LEFT AFFECTED AREA & LABOUR TO REPLACE ABOVE PARTS                           | New      | 500.00          | 200.00        |
| 4                               | TO PUTTY PRIMER & SPRAY PAINT ON FRT BUMPER ASSY & FRT TOWED COVER & FRT SENSOR 2K REARLESCENT PAINT | New      | 500.00          | 220.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                      |          | <b>1,160.00</b> | <b>485.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >