

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005559/T1EA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900021333
Claimant Vehicle No :	SKM8070X	Insured Vehicle No :	SMJ3417E
Date of Loss:	02/05/2021	Nature of Claim:	TP
		Claim No:	7955681692SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM8070X	Engine No:	08706435N54B30A
Make & Model:	BMW 335i, 3.0 (A)	Chassis No:	WBAWB72010P052154
Reg. Date:	04/05/2007 (Man. Year: 2007)	Odometer:	225053 km
Colour:	Blue		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	46,196.19	13,683.21	32,512.98	70.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	2,020.00	3,680.00	64.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,896.19	15,703.21	36,192.98	69.74
Approved Total (Overridden) (S\$)		12,550.00		
(S\$)	51,896.19	12,550.00	39,346.19	75.82
+ GST 7.00/7.00% (S\$)	3,632.73	878.50	2,754.23	75.82
Nett Amount (S\$)	55,528.92	13,428.50	42,100.42	75.82
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		14,135.95		
Global Sum Settlement (S\$)		14,130.00		

INSPECTION

Date of Assignment:	06/05/2021	RICO 60 AUTO SERVICES PTE LTD (HQ)
Date Inspected:	06/05/2021 Inspected At:	8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET BADGE	Necessary	133.00 FL	*133.00 FL
2	1		*BONNET SIDE LOCK	N/S Not Necessary / O/S Broken	708.00 FL	*202.00 FL
3	1		*BONNET SIDE BRACKET	Bent	275.00 FL	*175.00 FL
4	1		*BONNET SIDE LOCK CATCH	O/S Bent / N/S Not Necessary	264.80 FL	*69.30 FL
5	1		*BONNET CENTER HANDLE	Not Necessary	176.00 FL	*- FL
6	2		*BONNET ABSORBER	Not Necessary	532.00 FL	*- FL
7	2		*BONNET HINGE	Not Necessary	434.00 FL	*- FL
8	1		*FRONT BUMPER TOP RUBBER	Not Necessary	178.00 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER	N/S Not Necessary/ O/S Deformed	220.00 FL	*110.00 FL
10	1		*FRONT BUMPER SPRAY NOZZLE	Cracked	198.10 FL	*198.10 FL
11	1		*FRONT BUMPER SPRAY NOZZLE COVER	N/S Not Necessary / O/S Missing	157.80 FL	*78.90 FL
12	1		*FRONT BUMPER SPRAY NOZZLE HOSE	Cut	343.00 FL	*180.00 FL
13	1		*FRONT BUMPER TOW COVER	Not Necessary	123.00 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	744.00 FL	*644.00 FL
15	1		*FRONT BUMPER SIDE AIR ARCH RH	Deformed	355.40 FL	*225.00 FL
16	1		*FRONT BUMPER UNDER COVER	Not Necessary	355.40 FL	*- FL
17	4		*FRONT PARKING SENSOR	Missing (1 PCS ONLY)	1,424.00 FL	*265.00 FL
18	4		*FRONT PARKING SENSOR SEAL	Necessary	81.60 FL	*81.60 FL
19	1		*FRONT PARKING SENSOR WIRE HARNESS	Cut	977.50 FL	*577.50 FL
20	2		*FRONT GRILLE	Not Necessary	1,136.00 FL	*- FL
21	1		*FRONT GRILLE AIR ARCH	Deformed	245.00 FL	*245.00 FL
22	1		*FRONT GRILLE AIR ARCH INNER	Not Necessary	652.00 FL	*- FL
23	1		*HEAD LAMP	N/S Not Necessary / O/S Missing	4,776.20 FL	*2,200.00 FL
24	1		*HEAD LAMP BOTTOM BRACKET	N/S Not Necessary / O/S Cracked	558.80 FL	*120.00 FL
25	1		*SUPPORT PANEL	Cracked	1,422.00 FL	*728.75 FL
26	1		*BRACE PANEL	Not Necessary	255.70 FL	*- FL
27	1		*HORN	N/S Not Necessary / O/S Cracked	466.00 FL	*110.00 FL
28	1		*A/C CONDENSER	Not Necessary	2,114.00 FL	*- FL
29	1		*RADIATOR ASSY	Not Necessary	2,254.00 FL	*- FL
30	1		*RADIATOR FAN COWLING ASSY	Not Necessary	1,543.00 FL	*- FL
31	1		*ENGINE OIL COOLER	Bent	890.00 FL	*512.40 FL
32	2		*ENGINE OIL COOLER AIR DUCT	Missing (1 PCS ONLY)	250.00 FL	*125.00 FL
33	1		*TURBO INTERCOOLER	Not Necessary	939.00 FL	*- FL
34	1		*TURBO INTERCOOLER AIR ARCH	Not Necessary	178.00 FL	*- FL
35	1		*FRONT FENDER RH	Cracked	969.70 FL	*800.00 FL
36	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	456.00 FL	*- FL
37	1		*FRONT FENDER BRACKET RH	Bent	108.70 FL	*108.70 FL
38	1		*FRONT FENDER INNER SHIELD RH	Deformed	330.50 FL	*280.00 FL
39	1		*FRONT ABSORBER RH	Not Necessary	753.70 FL	*- FL
40	1		*FRONT LOWER ARM RH	Bent	454.60 FL	*254.60 FL
41	1		*FRONT CONTROL ARM RH	Not Necessary	444.50 FL	*- FL
42	1		*FRONT KNUCKLE ARM RH	Bent	614.20 FL	*414.00 FL
43	1		*FRONT WHEEL BEARING RH	Bent	555.20 FL	*355.00 FL
44	1		*FRONT ANTI ROLL BAR	Not Necessary	978.00 FL	*- FL
45	1		*FRONT ANTI ROLL BAR LINK RH	Not Necessary	215.00 FL	*- FL
46	1		*STEERING RACK ANF PINION	Not Necessary	3,086.70 FL	*- FL
47	1		*POWER STEERING OIL TANK	Not Necessary	211.00 FL	*- FL
48	1		*BONNET	Bent	4,000.00 FS	*2,200.00 FS
49	1		*FRONT BUMPER (M3)	Cracked	3,500.00 FS	*1,500.00 FS
50	1		*SET FRONT BUMPER CLIP	Necessary	75.00 FS	*30.00 FS
51	1		*SET FRONT BUMPER GRILLE	Not Necessary	500.00 FS	*- FS
52	1		*SET RADIATOR GRILLE CLIP	Not Necessary	40.00 FS	*- FS
53	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	90.00 FS	*20.00 FS
54	1		*FRONT WHEELHOUSING SEALANT	Not Necessary	80.00 FS	*- FS
55	1		*FRONT RIM RH	Cut	2,500.00 FS	*1,200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT TYRE RH	Not Necessary	600.00 FS	*- FS
57	1		*SIDE SKIRT RH	Not Necessary	2,000.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					47,923.10	14,142.85
- List Item Discount on L Items 5.00/5.00% (S\$)					1,726.91	459.64
Total Parts (S\$)					46,196.19	13,683.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	WIRING BULB CHECKING	New	150.00	30.00
4	REFOCUS HEADLAMP BEAM	New	250.00	30.00
5	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	0.00
6	DISMANTLE AND REPLACE A/C CONDENSER ASSY ,REFILL RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST	New	200.00	100.00
7	REMOVE AND REINSTALL RADIATOR ASSY ,PERFORMED RADIATOR PRESSURE TEST	New	200.00	0.00
8	REMOVE AND INSTALL FRONT PARKING SENSOR AND WIRING HARNESS ,PERFORM DISTANCE SENSORY INPUT TESTING	New	300.00	30.00
9	TO REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	800.00	150.00
10	TO CHECK FOUR WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			5,700.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >