

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21005560/R1BS3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	GBJ9147A	Insured Vehicle No :	SMA4955J
Date of Loss:	01/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002007

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ9147A		
Make & Model:	ISUZU NHR87AUE4AA, 1.9 D (M)	Engine No:	RZ4E10L793
Reg. Date:	04/10/2019 (Man. Year: 2019)	Chassis No:	JAANHR87EK7100157
Colour:	White	Odometer:	68203 km
Engine Capacity:	1898 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/75 R15	Rear Tyre Size:	155 R13C (D)
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,171.78	3,171.78	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	630.00	600.00	48.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,401.78	3,801.78	600.00	13.63
+ GST 7.00/7.00% (S\$)	308.12	266.12	42.00	13.63

Nett Amount (S\$)	4,709.90	4,067.90	642.00	13.63
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		4,696.90		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 06/05/2021

Estimated Period of Repair: 4.0 days

 Inspected At: Ethoz Group Ltd (HQ)
 30 Bukit Batok Crescent
 Singapore 658075
Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Sep 2021)	
Parts:	N/A	ISUZU NHR87AUE4AA 1.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ9147A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,434.00 FL	*1,434.00 FL
2	1		*FRONT BUMPER BRACKET RH	Bent	298.00 FL	*298.00 FL
3	1		*HEADLAMP RH	Cracked	1,344.00 FL	*1,344.00 FL
4	1		*SIDE LAMP RH	Cracked	362.00 FL	*362.00 FL
5	1		*FRONT DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*FRONT CORNER PANEL RH (NPA)	Not Necessary	0.00 FL	*- FL
7	1		*FRONT DOOR ADVERTISEMENT	Necessary	150.00 FS	*150.00 FS
8	1		*ROC STICKER	Necessary	20.00 FS	*20.00 FS
9	1		*FRONT DOOR STICKER RH	Necessary	93.51 FL	*93.51 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,701.51	3,701.51
- List Item Discount on L Items 15.00/15.00% (\$\$)	529.73	529.73
Total Parts (\$\$)	3,171.78	3,171.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	600.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	600.00	300.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (\$\$)			1,230.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >