

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21005567/DTF3E2

Date: 28/01/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29145180ACX
Claimant Vehicle No :	SHD4723E	Insured Vehicle No :	PC7292Y
Date of Loss:	05/05/2021	Nature of Claim:	TP
		Claim No:	635762

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4723E	Engine No:	G4LEKU296079
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU164428
Reg. Date:	06/08/2019 (Man. Year: 2019)	Odometer:	287799 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	DURATURN 5 mm	Rear Left Side:	DURATURN 5 mm
Front Right Side:	DURATURN 5 mm	Rear Right Side:	DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,539.18	13,478.92	18,060.26	57.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,300.00	2,710.00	3,590.00	56.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	37,839.18	16,188.92	21,650.26	57.22
+ GST 7.00/7.00% (S\$)	2,648.74	1,133.22	1,515.52	57.22
Nett Amount (S\$)	40,487.92	17,322.14	23,165.78	57.22

INSPECTION

Date of Assignment:	06/05/2021	
Date Inspected:	07/05/2021	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	7.0 days	

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jan 2022)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD4723E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID RUBBER	Deformed	187.40 FL	*187.40 FL
3	1		*BOOT LID HINGE (LH/RH)	O/S Bent / O/S Not Necessary	142.60 FL	*71.30 FL
4	2		*BOOT LID ABSORBER (LH/RH)	Serviceable	173.40 FL	*- FL
5	1		*BOOT LID LOCK UPPER	Damaged	224.00 FL	*224.00 FL
6	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
7	1		*EMBLEM-HYBRID	Necessary	24.30 FL	*24.30 FL
8	1		*EMBLEM-IONIQ	Necessary	31.30 FL	*31.30 FL
9	1		*REAR SPOILER	Broken	665.40 FL	*665.40 FL
10	1		*THIRD BRAKE LIGHT	Not Necessary	385.60 FL	*- FL
11	1		*BOOT HANDLE	Not Necessary	31.80 FL	*- FL
12	1		*BOOT LID LAMP (LH/RH)	O/S Broken /N/S Not Necessary	1,588.80 FL	*794.40 FL
13	1		*BOOT LID TRIMBOARD	Mtg Deformed	259.70 FL	*259.70 FL
14	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
15	1		*BOOT LID TRIMBOARD, CENTRE	Deformed	159.60 FL	*159.60 FL
16	1		*BOOT LID TRIMBOARD SIDE (LH/RH)	O/S Deformed/N/S Not Necessary	185.00 FL	*92.50 FL
17	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
18	1		*BOOT LID GLASS, UPPER	Not Necessary	907.20 FL	*- FL
19	1		*BOOT LID GLASS, LOWER	Broken	584.90 FL	*584.90 FL
20	1		*BOOT LID GLASS UPPER MOULDING	Not Necessary	186.30 FL	*- FL
21	1		*BOOT LID GLASS LOWER MOULDING	Not Necessary	145.20 FL	*- FL
22	1		*REAR BUMPER	Broken	459.40 FL	*459.40 FL
23	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
24	1		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	O/S Bent / N/S Not Necessary	376.20 FL	*188.10 FL
25	1		*ANTENNA ASSY-SMARTK OUTER	Not Necessary	689.50 FL	*- FL
26	1		*REAR BUMPER CENTRE MOULDING ASSY	Broken	451.25 FL	*451.25 FL
27	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Mtg Broken	47.50 FL	*47.50 FL
28	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
29	1		*REAR BUMPER SIDE RETAINER (LH/RH)	O/S Broken /N/S Not Necessary	171.60 FL	*85.80 FL
30	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
31	1		*REAR BUMPER UNDER CENTRE	Necessary	123.85 FL	*- FL
32	1		*REAR BUMPER SIDE UNDER (LH/RH)	O/S Broken /N/S Not Necessary	246.20 FL	*123.10 FL
33	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
34	1		*REAR BUMPER REFLECTOR LAMP (LH/RH)	O/S Cut / N/S Not Necessary	165.80 FL	*82.90 FL
35	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
36	1		*REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	Mtg Broken	328.60 FL	*328.60 FL
37	1		*LICENCE LAMP	Not Necessary	193.53 FL	*- FL
38	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*TAIL LAMP (RH)	Broken	870.40 FL	*870.40 FL
40	1		*TAIL LAMP QUARTER PANEL (RH)	Buckled	208.90 FL	*208.90 FL
41	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
42	1		*REAR PANEL GARNISH	Mtg Deformed	346.80 FL	*346.80 FL
43	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
44	1		*SPARE WHEEL LOCK NUT	Not Necessary	89.50 FL	*- FL
45	1		*SPARE TYRE PANEL	Not Necessary	892.50 FL	*- FL
46	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	863.50 FL	*- FL
47	1		*PANEL ASSY-REAR FLOOR SIDE (RH)	Repair	39.40 FL	*- FL
48	1		*REAR FLOOR CHASSIS MEMBER (RH)	Repair	1,863.40 FL	*- FL
49	1		*REAR TRAY TOOLS BOX LH	Broken	693.20 FL	*693.20 FL
50	1		*REAR TRAY LUGGS CENTER	Bent / Deformed	354.20 FL	*354.20 FL
51	1		*EXHAUST PIPE INSULATOR	Not Necessary	235.00 FL	*- FL
52	1		*EXHAUST SILENCER	Not Necessary	943.50 FL	*- FL
53	1		*EXHAUST PIPE HANGER	Not Necessary	29.20 FL	*- FL
54	1		*REAR FENDER (RH)	Buckled	1,768.30 FL	*1,768.30 FL
55	1		*REAR FENDER INNER PANEL (RH)	Repair	1,406.20 FL	*- FL
56	1		*REAR FENDER SHIELD REAR PIECE (RH)	Not Necessary	173.60 FL	*- FL
57	1		*RAER FENDER SHIELD FRT PIECE (RH)	Not Necessary	165.50 FL	*- FL
58	1		*REAR FENDER CORNER INNER UPPER GARNISH (RH)	Deformed	486.70 FL	*486.70 FL
59	1		*REAR FENDER AIR-DUCT (RH)	Deformed	87.30 FL	*87.30 FL
60	1		*REAR FENDER TRIM BOARD (RH)	Deformed	788.75 FL	*788.75 FL
61	1		*REAR FENDER TRIM BOARD TOP GARNISH (RH)	Deformed	167.90 FL	*167.90 FL
62	1		*ASSY BSD BLIND SPOT RADAR (RH)	Broken	1,625.00 FL	*1,625.00 FL
63	1		*WIRING HARNESS BWS EXT	Not Necessary	988.90 FL	*- FL
64	1		*REAR TYRE RIM (RH)	Not Necessary	1,124.20 FL	*- FL
65	1		*REAR WHEEL HUP-CAP (RH)	Not Necessary	346.40 FL	*- FL
66	1		*REAR WHEELBEARING & HUB ASSY	Not Necessary	554.00 FL	*- FL
67	1		*RAER TRAILING ARM (RH)	Not Necessary	265.40 FL	*- FL
68	1		*REAR ASSIST (RH)	Not Necessary	227.90 FL	*- FL
69	1		*REAR SHOCK ABSORBER (RH)	Not Necessary	230.50 FL	*- FL
70	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	133.10 FL	*- FL
71	1		*REAR ABSORBER STOPPER (RH)	Not Necessary	137.60 FL	*- FL
72	1		*REAR ABSORBER COVER (RH)	Not Necessary	175.60 FL	*- FL
73	1		*REAR CROSSMEMBER	Not Necessary	1,468.70 FL	*- FL
74	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
75	1		*STABILIZER LINK (RH)	Not Necessary	147.30 FL	*- FL
76	1		*REAR UPPER ARM (RH)	Not Necessary	239.50 FL	*- FL
77	1		*REAR LOWER ARM (RH)	Not Necessary	393.10 FL	*- FL
78	1		*REAR KNUCKLE ARM (RH)	Not Necessary	538.10 FL	*- FL
79	1		*REAR WIRING ASSY	Not Necessary	1,521.50 FL	*- FL
80	1		*REAR TRAY TOOLS BOX RH	Broken	675.30 FL	*675.30 FL
81	1		*REVERSE CAMERA ASSY	Not Necessary	983.20 FS	*- FS
82	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	35.00 FS	*35.00 FS
83	1		*BOOT LID COMFORT CABLINK TEL NO. STICKER	Not Necessary	30.00 FS	*- FS
84	1		*REAR NO. PLATE + TRIM COVER	Serviceable	45.00 FS	*- FS
85	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*92.00 FS
86	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
87	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
88	1		*SPARE TYRE PANEL TOP COVER SILICON	Serviceable	250.00 FS	*- FS
89	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,953.68	16,759.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	7,414.50	3,280.48
Total Parts (\$\$)	31,539.18	13,478.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE / REFIX UNDERCARRIAGE (RR)	New	400.00	0.00
10	RE-SET REAR ABS SYSTEM	New	400.00	0.00
11	REMOVE / REFIX FUEL TANK	New	80.00	0.00
12	REMOVE / REFIX EXHAUST PIPE	New	80.00	60.00
13	TRANSFER DOOR MECHANISM REAR	New	80.00	0.00
14	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
15	FOUR WHEEL ALIGNMENT	New	120.00	0.00
16	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
Gross Labour Cost (\$\$)			6,300.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >