

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21005569/BTF3E2

Date: 27/07/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/20-415721

Claimant Vehicle No : GBE2813H **Insured Vehicle No :** FBP9393Z

Date of Loss: 20/03/2021 Nature of Claim: TP Claim No: MSC/C/21-000155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE2813H**
Make & Model: MERCEDES-BENZ VITO 115, 2.1 D (A) Engine No: 64698051387932
Reg. Date: 10/10/2007 (Man. Year: 2007) Chassis No: WDF63970523350282
Colour: Silver Odometer: 383089 km
Engine Capacity: 2148 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R16 Rear Tyre Size: 225/60 R16
Front Left Side: MAIRUITU 5 mm Rear Left Side: MATRAC 5 mm
Front Right Side: MAIRUITU 5 mm Rear Right Side: MATRAC 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,733.30	3,569.80	1,163.50	24.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	850.00	770.00	47.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,353.30	4,419.80	1,933.50	30.43
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	6,353.30	3,550.00	2,803.30	44.12
+ GST 7.00/7.00% (S\$)	444.73	248.50	196.23	44.12
Nett Amount (S\$)	6,798.03	3,798.50	2,999.53	44.12

INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 07/05/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Jul 2021)	
Parts:	N/A	MERCEDES-BENZ VITO 115 2.1 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE2813H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,360.90 FL	*886.00 FL
2	1		*FRONT BUMPER RH SIDE BRACKET	Broken	93.80 FL	*93.80 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	837.52 FL	*837.52 FL
4	1		*RH HEADLAMP ASSY	Broken	894.00 FL	*680.00 FL
5	1		*FRONT APRON PANEL	Broken	448.62 FL	*448.62 FL
6	1		*FRONT GRILLE	Distorted	580.39 FL	*390.00 FL
7	1		*FRONT GRILLE EMBLEM	Necessary	128.01 FL	*68.00 FL
8	1		*FRONT RH FENDER	Broken	429.17 FL	*429.17 FL
9	1		*FRONT RH FENDER SPLASH SHIELD	Not Damaged	153.48 FL	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
11	1		*SET FRONT APRON PANEL CLIPS	Not Necessary	60.00 FS	*- FS
12	1		*FRONT RH FENDER STICKER	Necessary	180.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,225.89	3,953.11
- List Item Discount on L Items 10.00/10.00% (\$\$)	492.59	383.31
Total Parts (\$\$)	4,733.30	3,569.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	700.00	400.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	800.00	450.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	70.00	0.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	50.00	0.00
Gross Labour Cost (\$)			1,620.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >