LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21005570/BVF3E2

Date: 19/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700030505

Claimant Vehicle

No: SLR430E Insured Vehicle No: SLQ7432J

Date of Loss: 18/04/2021 Nature of Claim: TP Claim No: 5323674857SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR430E

 Make & Model:
 HONDA SHUTTLE, 1.5 G CVT (A)
 Engine No:
 L15B3539005

 Reg. Date:
 28/07/2017 (Man. Year: 2016)
 Chassis No:
 GK81007687

 Colour:
 Black
 Odometer:
 67638 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Habilead 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Habilead 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Date of Assignment: 06/05/2021

Yap Motor Services Pte Ltd (HQ)

Blk 7 #01-82 Sin Ming Road Industrial Estate

Singapore 575642

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan Manager: VERON CHEN

07/05/2021 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$60,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
3	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
4	1		*REAR LH FENDER	Dented	0.00 F	*- F
5	1		*REAR SHOCK ABSORBER	Bent	0.00 F	*- F
6	1		*REAR WHEEL BEARING	Jammed	0.00 F	*- F
7 E=Ers	1 anchise	nart	*REAR FENDER WHEEL COWLING	Broken	0.00 F	*- F
1 –110		purt.		Total Parts (S\$)	0.00	0.00
			Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >