4/5/22, 9:44 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21005579/EGA3Q2

05/04/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070179652 **Claimant Vehicle**

SG1754P Insured Vehicle No: SBP1188C No:

Date of Loss: 02/05/2021 Nature of Claim: TP Claim No: 8369824787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SG1754P

Make & Model: MAN NL320F (A22), 10.5 D ABS TURBO (A) 50350162875017 Engine No: Reg. Date: 19/06/2018 (Man. Year: 2018) Chassis No: WMAA22ZZ0JF006863

0 km Colour: Odometer: Multi-colour

Engine Capacity: 10518 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 Front Left Side: Rear Left Side: Goodyear 5 mm Goodyear 5 mm Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,982.68	1,232.44	5,750.24	82.35
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,362.00	1,927.00	435.00	18.42
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	9,344.68	3,159.44	6,185.24	66.19
	+ Loss of Use (5.0 x	S\$250.00/day) (S\$)	1,250.00		

+ Doc/Search Fee (S\$) 7.49 **Nett Liability (S\$)** 4,416.93 Global Sum Settlement (S\$) 4,400.00

INSPECTION

Date of Assignment: 06/05/2021

Strides Automotive Services Pte Ltd (Woodlands) 06/05/2021 Inspected At: Date Inspected:

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: **CHEN TSUE YEE** Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HINGE LH,SIDE FLAP,FOR MAN A22 BUS	Bent	362.40 F	*362.40 FL
2	2		*HINGE RH,SIDE FLAP,FOR MAN A22 BUS	Bent	362.40 F	*362.40 FL
3	1		*GAS SPRING 22N (4 PCS)	Bent (1 PCS ONLY)	379.60 F	*94.90 FL
4	4		*LATCH LEVER SEALED ,NON-LOCKING FOR ADL	Cut	549.68 F	*549.68 FL
5	1		*PANEL ,SIDE L10,WFRAME ,FOR MAN A22 BUS	Repair	980.40 F	*- FL
6	1		*PANEL ,SIDE L11,FOR MAN A22 BUS	Repair	1,092.50 F	*- FL
7	1		*N/S FRP REAR LAMP COVER	Repair	975.00 F	*- FL
8	1		*PANEL ,SIDE L8,FOR MAN A22 BUS	Repair	330.70 F	*- FL
9	1		*PANEL ,FRAME SIDE ,L10,FOR MAN A22 BUS	Repair	266.00 F	*- FL
10	1		*PANEL FRAME SIDE L11 ,FOR MAN A22 BUS	Repair	1,610.00 F	*- FL
11 	2	part. L=ListIt	*SEALANT SIKATACKMOVE TRANSPORTATION	Not Necessary	74.00 F	*- FL
-i ia	IIIOIIIGO	part. L-Listit	emble.	Sub Total (S\$)	6,982.68	1,369.38
			- List Item Discount or	n L Items 0.00/10.00% (S\$)	0.00	136.94
				Total Parts (S\$)	6,982.68	1,232.44
			Report was unsubmitted during th	is print-out.		

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	1,325.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	772.00	602.00
	Gross Labour Cost (S\$)		2,362.00	1,927.00
	Report was unsubmitted during the	is print-out.		

< END OF ESTIMATES >