

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21005588/GPA3Q2  
**Date:** 12/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
<b>Claimant Vehicle No :</b>	SHD1705C	<b>Insured Vehicle No :</b>	GBK3359P
Date of Loss:	06/05/2021	Nature of Claim:	TP
		Claim No:	5414071579SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD1705C</b>		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU156313
Reg. Date:	24/01/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU129587
Colour:	Silver	Odometer:	154763 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,690.80	954.56	736.24	43.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	400.00	1,280.00	76.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,370.80</b>	<b>1,354.56</b>	<b>2,016.24</b>	<b>59.81</b>
<b>+ GST 7.00/7.00% (S\$)</b>	235.96	94.82	141.14	59.82

<b>Nett Amount (S\$)</b>	<b>3,606.76</b>	<b>1,449.38</b>	<b>2,157.38</b>	<b>59.81</b>
<hr/>				
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$67.97/day) (S\$)		135.94		
+ Doc/Search Fee (S\$)		7.45		
<hr/>				
<b>Nett Liability (S\$)</b>		<b>1,692.77</b>		
<hr/>				
<b>Global Sum Settlement (S\$)</b>		<b>1,690.00</b>		
<hr/>				

INSPECTION

Date of Assignment: 07/05/2021

Date Inspected: 17/05/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)  
 23 Changi South Ave 2, #01-02  
 Singapore 486443

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
3	2		*REAR BUMPER REINFORCEMENT N/S & O/S LOWER BRACKET	Not Necessary	30.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT CENTRE LOWER BRACKET	Not Necessary	15.00 FL	*- FL
5	2		*REAR BUMPER N/S & O/S STAY	Not Necessary	276.20 FL	*- FL
6	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Not Necessary	66.20 FL	*- FL
7	1		*REAR BUMPER LOWER MOULDING CENTRE	Deformed	216.50 FL	*216.50 FL
8	1		*REAR BUMPER LIP	Not Necessary	47.50 FL	*- FL
9	1		*REAR BUMPER CAP HOOK	Not Necessary	9.10 FL	*- FL
10	2		*REAR BUMPER N/S & O/S REFLECTOR	Not Necessary	63.80 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
12	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
13	1		*REAR NUMBER PLATE WITH CASING	Cracked	50.00 FS	*50.00 FS
14	1		*REAR BUMPER TOP PROTECTOR	Necessary	80.00 FS	*80.00 FS
15	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
					<b>Sub Total (\$)</b>	<b>1,986.50</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>295.70</b>
					<b>Total Parts (\$)</b>	<b>1,690.80</b>
						<b>954.56</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	50.00	0.00
2	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	0.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ETC TO FACILITATE REPAIRS	New	180.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE END PANEL ETC	New	650.00	200.00
5	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL,REAR BUMPER LOWER COVER (BLACK)	New	600.00	200.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,680.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >