

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21005600/AVCN2**Date:** 14/09/2021**REFERENCE**

Insured/Claimant:	MELVIN HENG YAK WEE	Policy No:	2100285801-09	
Date of Loss:	28/04/2021	Nature of Claim:	OD	Claim No: 7340886908SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDQ6680K		
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Engine No:	CDN241282
Reg. Date:	12/01/2012 (Man. Year: 2011)	Chassis No:	WAUZZZ4G8CN083559
Colour:	White	Odometer:	167630 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$37,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,871.00	4,544.88	7,326.12	61.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,152.00	4,172.00	6,980.00	62.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,023.00	8,716.88	14,306.12	62.14
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	22,223.00	7,916.88	14,306.12	64.38
+ GST 7.00/7.00% (S\$)	1,555.61	554.18	1,001.43	64.38
Nett Amount (S\$)	23,778.61	8,471.06	15,307.55	64.38

INSPECTION

Date of Assignment:	07/05/2021		
Date Inspected:	05/05/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-LH	Dented	4,227.00 FS	*3,381.60 FS
2	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	124.00 FS	*- FS
3	1		*REAR DOOR OUTER SEAL	Necessary	231.00 FS	*184.40 FS
4	1		*REAR DOOR BONDING AGENT	Not Necessary	29.00 FS	*- FS
5	1		*REAR DOOR CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
6	1		*REAR DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
7	1		*REAR DOOR CATCH	Not Necessary	120.00 FS	*- FS
8	1		*REAR DOOR OUTER SEAL	Not Necessary	284.00 FS	*- FS
9	1		*REAR DOOR ROCKER MOULDING	Deformed	858.00 FS	*686.40 FS
10	1		*REAR DOOR ATTACHMENT PARTS-ADHESIVE TAPES	Necessary	16.00 FS	*12.48 FS
11	1		*REAR DOOR ATTACHMENT PARTS-CLIPS	Necessary	106.00 FS	*84.80 FS
12	1		*REAR DOOR SILL TRIM STRIP	Necessary	120.00 FS	*96.00 FS
13	1		*REAR SIDE PANEL-LH	Repair	4,532.00 FS	*- FS
14	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
15	1		*REAR RIM-LH (Npa)	Not Necessary	0.00 FS	*- FS
16	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
17	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
18	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
19	1		*SUNDRIES	Necessary	250.00 FS	*4.80 FS
20	1		*SILL TRIM STONE GUARD FILM	Necessary	118.00 FS	*94.40 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	11,871.00 4,544.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	400.00	280.00
2	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS	New	980.00	0.00
3	TO DISMANTLE AND RENEW LHS REAR DOOR AND LHS SILL PANEL TRIM.TO CUT OUT AND WELD LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,800.00	1,500.00
4	TO RESPRAY LHS REAR DOOR,LHS SILL PANEL TRIM,LHS REAR FENDER,DOOR ENTRANCE AND LHS SILL PANEL	New	4,500.00	2,200.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			11,152.00	4,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >