

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21005603/BTF3E2

Date: 01/09/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004222101		
Claimant Vehicle No :	SX4882T	Insured Vehicle No :	SLR9670U		
Date of Loss:	04/05/2021	Nature of Claim:	TP	Claim No:	SNM21D202619/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SX4882T	Engine No:	F1867581
Make & Model:	VOLKSWAGEN 1300, 1.3 (A)	Chassis No:	1102240666
Reg. Date:	04/01/1971 (Man. Year: 1970)	Odometer:	7236 km
Colour:	White		
Engine Capacity:	1285 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	165/50 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	ECONOMIST 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	ECONOMIST 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,717.50	3,750.57	6,966.93	65.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	900.00	1,100.00	55.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>12,717.50</b>	<b>4,650.57</b>	<b>8,066.93</b>	<b>63.43</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,700.00</b>		
<b>(\$\$)</b>	12,717.50	3,700.00	9,017.50	70.91
<b>+ GST 7.00/7.00% (\$\$)</b>	890.23	259.00	631.23	70.91
<b>Nett Amount (\$\$)</b>	<b>13,607.73</b>	<b>3,959.00</b>	<b>9,648.73</b>	<b>70.91</b>

### INSPECTION

Date of Assignment:	10/05/2021	
Date Inspected:	10/05/2021 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2021)
<b>Parts:</b>	143	VOLKSWAGEN 1300 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SX4882T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,300.00 FL	*1,899.60 FL
2	1		*BONNET UPPER EMBLEM	Necessary	138.00 FL	*131.05 FL
3	1		*BONNET LOWER EMBLEM	Necessary	155.00 FL	*131.05 FL
4	1		*BONNET VOLKSWAGEN WORDING EMBLEM	Necessary	248.00 FL	*112.60 FL
5	1		*BONNET LOWER CHROME HANDLE	Bent	361.00 FL	*120.00 FL
6	1		*BONNET CENTRE CHROME MOULDING	Bent	637.00 FL	*250.00 FL
7	1		*BONNET LOCK CATCH	Jammed	53.00 FL	*53.00 FL
8	1		*BONNET LOCK	Jammed	233.00 FL	*120.00 FL
9	1		*BONNET RH HINGE	Not Damaged	228.00 FL	*- FL
10	1		*BONNET LH HINGE	Not Damaged	228.00 FL	*- FL
11	1		*FRONT RH FENDER	Dented	1,505.00 FL	*851.00 FL
12	1		*FRONT RH FENDER LOWER CHROME MOULDING	No such part	163.00 FL	*- FL
13	1		*RH HEADLAMP ASSY	Distorted	834.00 FL	*414.00 FL
14	1		*RH HEADLAMP CHROME COVER	Dented	314.00 FL	*85.00 FL
15	1		*FRONT BUMPER	Not Damaged	1,700.00 FL	*- FL
16	1		*FRONT LH FENDER LOWER CHROME MOULDING	Repeated	163.00 FL	*- FL
17	1		*RH HEADLAMP ASSY	Repeated	834.00 FL	*- FL
18	1		*RH HEADLAMP CHROME COVER	Repeated	314.00 FL	*- FL
19	1		*SPARE TYRE OUTER COVER	Not Damaged	453.00 FL	*- FL
20	1		*SPARE TYRE GARNISH COVER	Not Damaged	683.00 FL	*- FL
21	1		*FRONT PANEL TOP RUBBER SEAL	Not Damaged	231.00 FL	*- FL
22	1		*FRONT NUMBER PLATE	Not Damaged	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,895.00</b>	<b>4,167.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,177.50	416.73
<b>Total Parts (\$\$)</b>	<b>10,717.50</b>	<b>3,750.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	800.00	500.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	0.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	80.00	0.00
5	CHECK, ADJUST AND REFOCUS HEADLAMPS ASSY	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >