

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21005607/ETF3E2

**Date:** 16/06/2021

### REFERENCE

Insured/Claimant: HO THIAM POH Policy No: 2000002176  
Date of Loss: 06/05/2021 Nature of Claim: OD Claim No: 7971582197SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR6792J**  
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UJK2765  
Reg. Date: 17/01/2020 (Man. Year: 2019) Chassis No: MMBSTA13AKH004801  
Colour: Grey Odometer: 36923 km  
Engine Capacity: 1193 cc  
Market Value/New Car Price: S\$66,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15  
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm  
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,719.51	7,450.38	3,269.13	30.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,400.00	7,040.00	1,360.00	16.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>19,119.51</b>	<b>14,490.38</b>	<b>4,629.13</b>	<b>24.21</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,338.37</b>	<b>1,014.33</b>	<b>324.04</b>	<b>24.21</b>
<b>Nett Amount (S\$)</b>	<b>20,457.88</b>	<b>15,504.71</b>	<b>4,953.17</b>	<b>24.21</b>

### INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 07/05/2021 Inspected At:

Estimated Period of Repair: 12.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	5		*CLIP,FR BUMPER	Necessary	20.00 FL	*20.00 FL
2	1		*FACE,FR BUMPER	Broken	706.00 FL	*706.00 FL
3	1		*MARK,THREE-DIA	Not Necessary	70.00 FL	*- FL
4	1		*COVER,HEADLAMP SUPT PANEL	Not Necessary	62.00 FL	*- FL
5	1		*GRILLE,FR UNDER	Not Necessary	165.00 FL	*- FL
6	1		*GARNISH,FR BUMPER,RH	Cut	127.00 FL	*127.00 FL
7	1		*BRACKET,FR BUMPER,RH	Missing	13.00 FL	*13.00 FL
8	1		*BRACKET,FR BUMPER,LH	Not Necessary	13.00 FL	*- FL
9	1		*AID DAM,SIDE,FR RH	Not Necessary	18.00 FL	*- FL
10	1		*GRILLE,RADIATOR	Not Necessary	557.00 FL	*- FL
11	1		*FENDER,FR RH	Dented	500.00 FL	*500.00 FL
12	1		*SHIELD,FR WHEELHOUSE,RH	Not Necessary	98.00 FL	*- FL
13	1		*CLIP,FR BUMPER	Necessary	4.00 FL	*4.00 FL
14	1		*HINGE,HOOD,LH	Not Necessary	56.00 FL	*- FL
15	1		*HINGE,HOOD,RH	Not Necessary	56.00 FL	*- FL
16	1		*HOOD	Dented	737.00 FL	*737.00 FL
17	1		*INSULATOR,HOOD	Crushed	177.00 FL	*177.00 FL
18	6		*CLIP,HOOD INSULATOR	Necessary	18.00 FL	*18.00 FL
19	1		*LATCH,HOOD	Not Necessary	69.00 FL	*- FL
20	1		*HEADLAMP ASSY,RH	Broken	663.00 FL	*663.00 FL
21	1		*COVER,DOOR MIRROR,OTR RH	Repair	115.00 FL	*- FL
22	1		*TAPE,FR DOOR SASH,RH	Necessary	29.00 FL	*29.00 FL
23	1		*TAPE,RR DOOR SASH,RH	Necessary	29.00 FL	*29.00 FL
24	1		*CROSSMEMBER,FR AXLE,NO 1	Not Necessary	868.00 FL	*- FL
25	1		*ARM ASSY,FR SUSP,LWR RH	Not Necessary	280.00 FL	*- FL
26	1		*WHEEL,DISC	Cut	687.00 FL	*687.00 FL
27	1		*BEARING,FR WHEEL HUB	Not Necessary	122.00 FL	*- FL
28	1		*SNAP RING,FR WHEEL HUB	Not Necessary	8.00 FL	*- FL
29	1		*PANEL ASSY,FR END	Not Necessary	1,055.00 FL	*- FL
30	1		*PANEL,HEADLAMP SUPPORT,UPR	Not Necessary	66.00 FL	*- FL
31	1		*TANK,WINDSHIELD WASHER	Not Necessary	75.00 FL	*- FL
32	1		*PAD,FR SUSP SPRING	Not Necessary	17.00 FL	*- FL
33	1		*INSULATOR,FR SUSP STRUT	Not Necessary	99.00 FL	*- FL
34	1		*GEAR & LINK ASSY,STEERING	Bent	1,459.00 FL	*1,459.00 FL
35	1		*BODY KIT ATTRAGE	Broken	1,643.00 FS	*1,643.00 FS
36	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
37	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
38	1		*FRONT RH TYRE	Not Necessary	260.00 FS	*- FS
39	1		*PANEL ASSY, FR DOOR, RH	Dented	1,001.00 FL	*1,001.00 FL
			(Supplementary)			
40	1		*CROSSMEMBER, FR AXLE, NO.1	Bent	868.00 FL	*868.00 FL
			(Supplementary)			
41	1		*STRUT, FR SUSP	Bent	456.00 FL	*456.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,333.00</b>	<b>9,174.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (\$\$)</b>	2,613.49	1,723.62
<b>Total Parts (\$\$)</b>	<b>10,719.51</b>	<b>7,450.38</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER,BONNET,FRT RH FENDER,SUPPORT,FRT RH DOOR,REAR RH DOOR & AFFECTED AREAS.REPAIR ON REAR RH FENDER,REAR BUMPER & FRT RH FENDER EXTENSION	New	3,150.00	2,250.00
2	SPRAY ON FRT BUMPER,BONNET,FRT RH FENDER,SUPPORT,FRT RH DOOR,REAR RH DOOR,REAR RH FENDER,REAR BUMPER,RH WING MIRRRO COVER,BODYKIT & FRT RH FENDER EXTENSION	New	3,500.00	3,500.00
3	REMOVE AND INSTALL FRT RADIATOR SUPPORT TO FACILITATE REPAIE	New	120.00	0.00
4	TO TOP UP AIRCON GAS	New	80.00	0.00
5	TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL	New	120.00	120.00
6	TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL	New	120.00	0.00
7	TO REPLACE DAMAGED BODYKIT	New	240.00	240.00
8	REMOVE AND INSTALL REAR PARKING ASSIST	New	120.00	60.00
9	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	80.00
10	PERFORM RUST PREVENTION	New	120.00	40.00
11	TO REPLACE FRT UNDERCARRIAGE	New	450.00	450.00
12	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
13	TO TRANSFER FRONT RH RIM INCLUDING BALANCING	New	30.00	30.00
14	CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
15	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
			<b>Gross Labour Cost (\$\$)</b>	<b>8,400.00</b>
				<b>7,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >