

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 1977014696

FSTIMATE

GST Reg No : MR-8500111-X

 231,014036	ESTIMATE	GST REG NO . HR GSGGIII A				
Invoice Name & Address		Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model	KCV15293/HO THIAN POH SMR6792J / 17/01/202 07/05/2021/ 0 MMBSTA13AKH004801 3A92UJK2765 MIT/19MY ATTRAGE 1.2 CVT U01 TITANIUM GREY M/ BK BLACK				

Account No		Data Maria Data da	CSE	Operator		WIP No	i ki T		
Account No	Terms	Date/Time Printed		289 / Patrick L	ee	10822			
KAX00008	Credit		QUK		Qty	Unit Price	Disc%		ount
1997 1980									150.00
E PNTSSOCO REPLACE I REAR RH I REPAIR OI E PNT98000 SPRAY ON RHIDOOR, & FRT RH E PNT88000 REMOVE AM M SUNDRY TO TOP UP E PNT88000 TO TRANSF E PNT88000 TO TRANSF E PNT88000 TO TRANSF	FRT BUMPE DOOR & AF I REAR RH FRT BUMP REAR RH FENDER E ID INSTAL AIRCON ER FRT RI ER REAR I	Description of Good R, BONNET, FRT RH F FECTED AREAS FER, BONNET, FRT RH FENDER, REAR BUMPER XTENSION L FRT RADIATOR SUPP GAS H DOOR ATTACHMENTS D BODYKIT C FISH 1	ENDER, SUPI R & FRT RH FENDER, SUI , RH WING I ORT TO FACTOR TO NEW PAN	PORT, FRT RH DOOR, FENDER EXTENSION PORT, FRT RH DOOR MIRROR COVER, BODY CLITATE REPAIR NEL	Qty S X 4 REAR KIT, 3	350 X 10 350 X 10 (1007 Spoiler)	Disc%	2250°	120.00, 80.00
REMOVE AND		REAR PARKING ASSI	ST					40	80.0
SUNDRY PERFORM RU									450.0
33900099 TO REPLACE	FRT UND	ERCARRIAGE							120.0
	Compute	rize Full Wheel Ali	ignment						30.0
	R FRONT	RH RIM INCLUDING BA	ALANCING						30.0
54900099 CHECK ON N	IRING &	CHASSIS ELECTRICAL	SYSTEM						120.0

Confirm & accepted by

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Colour/Trim

Co Reg No : 197701469G

ESTIMATE	GST Reg No : MR-8500111-X
	Owner Name & Vehicle Info
Cust No/Name	KCV15293/HO THIAN POH
Reg No/Reg Date	SMR6792J / 17/01/202
Date In/Mileage	07/05/2021/ 0
Chassis No	MMBSTA13AKH004801
Engine No	3A92UJK2765
Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No

UO1 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	07/05/2021/ 14:23	QUK	289 / Patrick	Lee	10822		
NANOCCO	Credit	Description of Good			Qty	Unit Price D	isc% Am	ount
TO CARRY	OUT DIAG	NOSTIC CHECK USING I	II-SCAN PR	O TEST			ه ا	
USING HI-	SCAN PRO) 1F21					1	260.00
M SUNDRY TO SUPPL	V EDONT	DU TYPE					20	50.00
M SUNDRY	FRONT	KII TINE					1 2 0	50.00
SUNDRIES		44.6			5 00	4.00	23 00	15.40
1 CLIP, FR B	UMPER /	r RC			5.00 1.00	706.00		543.62
FACE, FR B		OK.			1.00	70.00	23.00	53.90
MARK THRE	E-DIA	X AM			1.00	62.00	23.00	47.7
COVER, HEA	DLAMP SU	PT PANEL X MIN		П	1.00	165.00	23.00	127.0
GRILLE, FR	UNDER	X MM CUT		TI TOO	T 1.00	127.00		97.7
GARNISH, FI	S BUMPER	-4	211	1110012	1.00	13.00	23.00	10.0 10.0
BRACKET, FF	BUMPER	No. 3 . I many	<u>ک) ال</u>	$\Pi\Pi\Pi\Pi\Pi\Pi$	21 (1.00	13.00	23.00	13.
BRACKET, FF	DE ED DI	La de la company			1.00	18.00 557.00	23.00	428.
GRILLE, RAD		· ? XMM			1.00		23.00	385.
FENDER, FR		00			1.00	17.00	00.00	17.
EMBLEM ECO		/ 185			1.00 1.00	98.00	23.00	75.
SHIELD, FR	WHEELHOL	ISE, RH ? X MM			1.00		23.00	3.
CLIP, FR BU	MPER /	- ηες			1.00	56.00	23.00	43.
HINGE, HOOD	,LH 🗶	NM			1.00	56.00	23.00	43.
HINGE, HOOD	,RH X	VIW			1.00	737.00	23.00	567.
HOOD /	0 0	-01			1.00	177.00	23.00	136.
INSULATOR,	H00D 🖌	CRU			6 1 00		23.00	2.
CLIP, HOOD	INSULATO	R / NC			1.00	69.00		53.
LATCH, HOOD	X MI	OR		1.01/20)	1.00	663.00		510
HEADLAMP AS			RH Spaler	DIOKET)	1.00	1643.00	00.00	1643 88
BODY KIT A	TTRAGE	OTR RH X R	3.E		1.00	115.00		22
COVER, DOOR	MIRROR,				1.00		23.00	22
TAPE, FR DO	JK SASH,	nu - nec			1.00	29.00		668
TAPE, RR DO)K 5A5H,	A	1		1.00	868.00 280.00		215
CROSSMEMBER	C, PK MAL		L /		1.00	280.00	23.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered and additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. any aggittional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the repair requiring the moneyal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel. 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info					
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16	Cust No/Name KCV15293/HO THIAN POH Reg No/Reg Date SMR6792J / 17/01/202 Date In/Mileage 07/05/2021/ 0 Chassis No MMBSTA13AKH004801					
AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Engine No 3A92UJK2765 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK					

Account No Te	arme	Date/Time Printed	CSE	Ope	rator		e-a-1 mann pro	WIP No			
	redit		OUK	289	/ Patric	k Lee		10822			
NAXUUUU Cr	eart	Description of Goods		1000	<u> </u>		Qty	Unit Price		Am	ount
			7 00111000				1.00	687.00			528.99
M WHEEL, DISC	0,55	Cut (FM RM)					1.00	122.00			93.94
M BEARING, FR W M SNAP RING, FR							1.00	8.00	23.00		6.16
							1.00	1055.00	23.00		812.35
M PANEL ASSY,F M PANEL,HEADLA	WD CITE	PRIT UPR X NA					1.00		23.00		50.82 57.75
M TANK, WINDSHI	FID MA	ACHER 'Y X M'M'					1.00		23.00		13.09
M PAD, FR SUSP	SPRING						1.00		23.00		76.23
M INSULATOR, FR	SUSP						1.00	99.00	23.00	/	1123.43
4 GEAR & LINK	ASSY.S	TEERING / OT					1.00	1459.00	23.00		1123.4
			Sten Sten			00- N EXCUI P/P M					

Confirm & accepted by

7% GST on 17317.71

17,317.71 1212.24

Total Payable

18,529.95

Authorized signatory and company stamp

Yalidity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.