

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21005608/DVF3E2

**Date:** 30/08/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00008242000  
Claimant Vehicle No: SJT5890R Insured Vehicle No: PA8513P  
Date of Loss: 05/05/2021 Nature of Claim: TP Claim No: SNM21D202637/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT5890R**  
Make & Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A) Engine No: G4FC9U746879  
Reg. Date: 21/10/2009 (Man. Year: 2009) Chassis No: KMHDU41BMAU893844  
Colour: Silver Odometer: 265432 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Premio 5 mm Rear Left Side: Premio 5 mm  
Front Right Side: Premio 5 mm Rear Right Side: Premio 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	38,143.20	3,229.68	34,913.52	91.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,400.00	2,090.00	9,310.00	81.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>49,543.20</b>	<b>5,319.68</b>	<b>44,223.52</b>	<b>89.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>(S\$)</b>	49,543.20	4,200.00	45,343.20	91.52
<b>+ GST 7.00/7.00% (S\$)</b>	3,468.02	294.00	3,174.02	91.52
<b>Nett Amount (S\$)</b>	<b>53,011.22</b>	<b>4,494.00</b>	<b>48,517.22</b>	<b>91.52</b>

### INSPECTION

Date of Assignment: 07/05/2021  
Date Inspected: 08/05/2021 Inspected At: JWG International Pte Ltd (HQ)  
Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK  
AutoPoint  
Singapore 568047  
Estimated Period of Repair: 6.0 days

**Adjuster:** BRYAN TANI

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2021)

**Parts:** 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJT5890R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Not Necessary	1,789.00 FL	*- FL
2	1	*BONNET INSULATOR	Not Necessary	210.00 FL	*- FL
3	1	*BONNET SEAL	Not Necessary	129.00 FL	*- FL
4	1	*BONNET LOCK	Not Necessary	198.00 FL	*- FL
5	1	*HEAD LAMP LH / RH	O/SMtgBroken/N/SSNot Necessary	3,220.00 FL	*581.60 FL
6	2	*HEAD LAMP LOWER BRACKET LH / RH	Not Necessary	218.00 FL	*- FL
7	1	*HEAD LAMP WIRE HARNESS	Not Necessary	1,292.00 FL	*- FL
8	1	*FRONT GRILLE	Not Necessary	519.00 FL	*- FL
9	1	*FRONT GRILLE CHROME	Not Necessary	429.00 FL	*- FL
10	1	*FRONT BUMPER	Distorted / Mtg Broken	802.00 FL	*461.00 FL
11	2	*FRONT BUMPER FOG LAMP GARNISH LH / RH	Not Necessary	556.00 FL	*- FL
12	1	*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	1,130.00 FL	*- FL
13	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	490.00 FL	*- FL
14	1	*FRONT BUMPER UNDER COVER	Not Necessary	310.00 FL	*- FL
15	2	*FRONT BUMPER SIDE RETAINER LH / RH	Not Necessary	190.00 FL	*- FL
16	1	*FRONT BUMPER SPONGE	Torn	423.00 FL	*118.60 FL
17	1	*FRONT REINFORCEMENT BAR	Serviceable	992.00 FL	*- FL
18	1	*FRONT SUPPORT PANEL	Not Necessary	1,780.00 FL	*- FL
19	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	371.00 FL	*- FL
20	1	*FRONT BRACE PANEL	Not Necessary	198.00 FL	*- FL
21	1	*A/C CONDENSOR	Not Necessary	1,590.00 FL	*- FL
22	1	*A/C CONDENSOR DISCHARGE PIPE	Not Necessary	491.00 FL	*- FL
23	1	*A/C CONDENSOR SUCTION PIPE	Not Necessary	781.00 FL	*- FL
24	1	*RADIATOR ASSY	Not Necessary	1,882.00 FL	*- FL
25	1	*RADIATOR FAN MOTOR	Not Necessary	450.00 FL	*- FL
26	1	*RADIATOR FAN BLADE	Not Necessary	214.00 FL	*- FL
27	1	*RADIATOR FAN COWLING	Not Necessary	410.00 FL	*- FL
28	1	*BOOTLID	Repair	1,681.00 FL	*- FL
29	2	*BOOTLID LAMP LH / RH	Not Necessary	698.00 FL	*- FL
30	1	*BOOTLID INNER TRIM	Not Necessary	590.00 FL	*- FL
31	1	*BOOTLID WEATHER STRIP	Necessary	310.00 FL	*165.30 FL
32	2	*BOOTLID HINGE LH / RH	Not Necessary	238.00 FL	*- FL
33	1	*BOOTLID LOCK	Serviceable	301.00 FL	*- FL
34	1	*BOOTLID CYLINDER LOCK	Not Necessary	294.00 FL	*- FL
35	1	*BOOTLID NO. PLATE TOP GARNISH	Not Necessary	385.00 FL	*- FL
36	2	*BOOTLID NO. PLATE LAMP LH / RH	Not Necessary	178.00 FL	*- FL
37	1	*BOOTLID LOGO	Serviceable	72.00 FL	*- FL
38	1	*BOOTLID AVANTE EMBLEM	Serviceable	88.00 FL	*- FL
39	1	*BOOTLID S EMBLEM	Serviceable	69.10 FL	*- FL
40	1	*TAIL LAMP LH / RH	N/SMtg Cracked/O/SSNotNecessary	1,396.00 FL	*346.10 FL
41	2	*TAIL LAMP LOWER BRACKET LH / RH	Not Necessary	396.00 FL	*- FL
42	1	*REAR BUMPER	Dented	828.00 FL	*486.90 FL
43	2	*REAR BUMPER SIDE RETAINER LH / RH	Serviceable	164.00 FL	*- FL
44	1	*REAR BUMPER SPONGE	Broken	210.00 FL	*119.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR REINFORCEMENT BAR	Cracked	994.00 FL	*354.00 FL
46	2		*REAR BUMPER REFLECTOR LH / RH	Not fitted	198.00 FL	*- FL
47	5		*REAR BUMPER BRACKET	Not Necessary	395.00 FL	*- FL
48	1		*REAR BUMPER UNDER COVER	Not Necessary	342.00 FL	*- FL
49	1		*REAR END PANEL	Dented	1,140.00 FL	*585.30 FL
50	1		*REAR END PANEL TOP GARNISH	Not Necessary	380.00 FL	*- FL
51	1		*SPARE WHEEL PANEL	Not Necessary	1,692.00 FL	*- FL
52	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	549.00 FL	*- FL
53	2		*SPARE WHEEL QUARTER PANEL LH / RH	Not Necessary	1,180.00 FL	*- FL
54	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	483.00 FL	*- FL
55	2		*REAR FENDER LH / RH	Not Necessary	4,002.00 FL	*- FL
56	1		*REAR FENDER INNER TRIM LH / RH	O/S Bent / N/S Not Necessary	1,978.00 FL	*327.20 FL
57	1		*REAR WHEEL HOUSING LH	Not Necessary	1,429.00 FL	*- FL
58	1		*REAR EXHAUST PIPE	Not Necessary	1,728.00 FL	*- FL
59	1		*REAR EXHAUST MOUNTING	Not Necessary	98.30 FL	*- FL
60	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	299.00 FL	*- FL
61	1		*REAR REINFORCEMENT BAR BRACKET LH	Bent	92.10 FL	*92.10 FL
62	1		*FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
63	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
64	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
65	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
66	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
67	1		*COOLANT	Not Necessary	100.00 FS	*- FS
68	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
69	1		*BOOTLID LAMP CLIPS	Not Necessary	50.00 FS	*- FS
70	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
71	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
72	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
73	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
74	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
75	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
76	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
77	1		*FRONT & REAR NO. PLATE & CASING	Not Necessary	200.00 FS	*- FS
78	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>47,331.50</b>	<b>3,957.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	9,188.30	727.42
<b>Total Parts (S\$)</b>	<b>38,143.20</b>	<b>3,229.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
<b>Labour Items</b>					
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00	
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,000.00	500.00	
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,000.00	400.00	
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	2,400.00	500.00	
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	2,400.00	500.00	
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00	
7	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00	
8	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00	
9	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00	
10	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	0.00	
11	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00	
12	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	150.00	0.00	
13	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00	
14	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00	
15	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00	
			<b>Gross Labour Cost (\$\$)</b>	<b>11,400.00</b>	<b>2,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >