

SERVICE ESTIMATE

99831 - C00018 SL: SERVICE/PARTS SALES - DUCATI

Mr Teo Zhi Hao
14 Cactus Drive
#04-01

Inv.No. ... : D 0 Page 1

Inv.date ... : 06/05/2021

WIP No. ... : 23437

Veh. In/Out:

*Tel.No. ... : Mobile: 84681641

Reg.No. ... : FBP8445P / DVL

Reg.date ... : 20/06/2019

Mileage ... : 0

Chassis No.: ZDMGE00AAKB000403

Variant... : DIAVELI260S

Singapore
Singapore 809689

Closed by : Tony Alfred Desire D

Svc Consultant : 0762

Remarks : Mr Teo Zhi Hao

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
NOTES	Customer Highlight				0.00	0			S
	- Accident repair								
000	Receive Pre-booked Customer				0.20	0		0.20	S
DUCT-A	Accident Damage Assessment				70.00	0		70.00	S
DUCC-1	To replace damaged parts caus				3600.00	0		3600.00	S 2400 /
DUCT-S	Insurance particulars research				7.50	0		7.50	S
	SIDE STAND ?			1.0 EA	178.20			178.20	S /
	AXLE, SIDE STAND			1.0 EA	13.00			13.00	S /
	NUT			1.0 EA	5.90			5.90	S /
	STEERING HEAD B			1.0 EA	686.30			686.30	S /
	SEAL RING ?			2.0 EA	10.90			21.80	S /
	WASHER ?			1.0 EA	4.10			4.10	S /
	BEARING, STEER			2.0 EA	85.80			171.60	S /
	STEERING HEAD ?			1.0 EA	544.30			544.30	S /
	VIBRATION DAMPE			2.0 EA	21.20			42.40	S /
	WASHER 6.4X16X			6.0 EA	0.40			2.40	S X
	SCREW TCEI M6X			2.0 EA	1.30			2.60	S /
	CLAMP ?			7.0 EA	0.40			2.80	S
	FORK LEG ASSY, ?			1.0 EA	3076.10			3076.10	S
	FORK LEG ASSY, ?			1.0 EA	3216.30			3216.30	S /
	REFLECTOR, ADHE			2.0 EA	9.10			18.20	S /
	SCREW			7.0 EA	1.00			7.00	S
	SCREW TCEIR M6			5.0 EA	1.10			5.50	S
	VIBRATION DAMP			4.0 EA	2.50			10.00	S /

NN
nec

SERVICE ESTIMATE

99831 - C00018
 Mr Teo Zhi Hao
 14 Cactus Drive
 #04-01

SL: SERVICE/PARTS SALES - DUCATI

Inv.No. : 0 Page 2

Inv.date : 06/05/2021

WIP No. : 23437

Veh. In/Out:

*Tel.No. : Mobile: 84681641

Reg.No. : FBP8445P / DVL

Reg.date : 20/06/2019

Mileage : 0

Chassis No.: ZDMGE00AAKB000403

Variant... : DIAVEL1260S

Singapore 809689
 Singapore 809689

Closed by : Tony Alfred Desire D

Svc Consultant : 0762

Remarks : Mr Teo Zhi Hao

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	FRONT FENDER, B <i>Xsm</i>	1.0	EA		343.10			343.10	S
	DECAL DUCATI SA <i>Xsm</i>	1.0	EA		16.60			16.60	S
	DECAL DUCATI SA <i>Xsm</i>	1.0	EA		16.60			16.60	S
	SPACER 6.2X8.5X <i>Xsm</i>	4.0	EA		3.80			15.20	S
	SCREW, TAPPING <i>Xsm</i>	1.0	EA		0.90			0.90	S
	FRONT WHEEL RIM <i>? bt</i>	1.0	EA		2200.60			2200.60	S ✓
	FRONT BRAKE DIS <i>Xsm</i>	2.0	EA		495.30			990.60	S
	VALVE, TUBELESS <i>? ne</i>	1.0	EA		20.30			20.30	S ✓
	SCREW <i>ne</i>	10.0	EA		2.30			23.00	S ✓
	FRONT WHEEL SPI <i>? sc</i>	1.0	EA		239.00			239.00	S ✓
	SEAL RING <i>? xsm</i>	1.0	EA		10.70			10.70	S
	INNER SPACER <i>? xsm</i>	1.0	EA		35.70			35.70	S
	SEAL RING <i>? ne</i>	1.0	EA		35.80			35.80	S ✓
	BEARING <i>? ne</i>	2.0	EA		42.70			85.40	S ✓
	C RING <i>? ne</i>	1.0	EA		22.20			22.20	S ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Passer
Hg 90010068
2 days
10/05/21 @ 1135
Resy after repair

Labour Total 3,677.70
 Parts Total 12,064.20
 Package Total 0.00

Amount 15,741.90
 GST @ 7 % 1,101.93
 Total Amount 16,843.85
 Less Amt Paid 0.00
 Nett Amount 16,843.85

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Service Estimates are valid for 10 days from the above date.

This is a computer generated invoice, no signature is required.