



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 1451E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	DENTED		
	RH DECK SIDE LOWER PANEL		945.50	356.00
	LESS 25% DISCOUNT		-236.37	-89.00
			709.13	267.00
	<u>SPECIAL NETT ITEMS</u>			
	1 RH DECK SIDE LOWER PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
	1 RH DECK SIDE LOWER PANEL RIVET (SN)	NOT NECESSARY	60.00	-
			180.00	-
	<u>LABOUR</u>			
	TO PANEL BEAT,WELD,CUT,ADJUST,KNOCK.		400.00	300.00
	TO PUTTY,SPRAY PAINT,POLISH WAX.		300.00	200.00
			700.00	500.00
GRAND TOTAL			1,589.13	767.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				600.00

Report Ref No. CS/AGI21005613/Buf3n2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.