



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 4713R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	DENTED	1,200.00	1,020.00
1	FRONT GRILLE ASSY	BROKEN	350.00	350.00
1	FRONT BUMPER	DENTED	475.00	475.00
1	FRONT BUMPER REINFORCEMENT	BENT	330.86	210.00
1	FRONT BUMPER LOWER GRILLE CENTRE	BROKEN	225.00	225.00
	LESS 25% DISCOUNT		-645.22	-570.00
			1,935.64	1,710.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BENT	40.00	40.00
			40.00	40.00
	<b><u>LABOUR</u></b>			
	SPRAY PAINTING FRONT ACCIDENT DAMAGED AREAS.		850.00	400.00
	TO REPAIR RADIATOR SUPPORT PANEL, FRONT INNER PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS.		700.00	400.00
			1,550.00	800.00
	<b>GRAND TOTAL</b>		<b>3,525.64</b>	<b>2,550.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,050.00</b>

Report Ref No. CS/AWA21005615/Etf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.