

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No. 199607	198R GST Reg. No. 19-	-9007190-K		
Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIED WORLD A	SSURANCE COMPANY LTD	Re	ef: CS/AWA21005615/Etf3e2	2	
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 0799	#08-01 (8th FLOOR) ON	Da	ate: 11/06/2021		
			Co	ode: AWA		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YN 5695S	Veh. Inspected	GBB 4713R		
	Policy No.	NSV1900528/HLF	Coverage (\$)	0.00		
	Claim No.	AVCPSB0064951905	Excess (\$)	0.00		
	Assign From	PEGGY CHAN	Assign Date	07/05/2021		
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HILUX	c.c	2982		
	Engine No.	HIDDEN	Year of Reg.	2009		
	Chassis No.	MR0EZ12G004006578	Colour	WHITE		
	Odometer	382489 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	FAIR				
3.	. Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	205/70 R15C	YOKOHAMA	5 mm		
	L/H Front Tyre	205/70 R15C	YOKOHAMA	5 mm		
	R/H Rear Tyre	205/70 R15C	YOKOHAMA	5 mm		
	L/H Rear Tyre	205/70 R15C	YOKOHAMA	5 mm		
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/10/2019	Inspection Date	17/05/2021		
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD				
		BLK 8 PANDAN LOOP SINGAPORE 128226				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: