

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG17020351/R1PA3Q2-1

Date:

18/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SKD1838S

Date of Loss: 19/10/2017

Policy No:

Insured Vehicle No :

Nature of Claim:

SKF9321C

TP

Claim No:

1965709510SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKD1838S**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Reg. Date: 01/11/2011 (Man. Year: 2011)

Colour: Grey

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No:

HIDDEN

Chassis No:

MR053REE104125818

Odometer:

120032 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Handbrake (Serviceable):

Yes

Steering (Serviceable):

Engine Modification:

Yes

No

Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Tyre Size:

195/65 R15

Rear Left Side:

West Lake 5 mm

Rear Right Side:

West Lake 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,977.54	2,946.20	3,031.34	50.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,600.00	600.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,177.54	4,546.20	3,631.34	44.41
Approved Total (Overridden) (S\$)		3,600.00		

(S\$)	8,177.54	3,600.00	4,577.54	55.98
+ GST 7.00/7.00% (S\$)	572.43	252.00	320.43	55.98
Nett Amount (S\$)	8,749.97	3,852.00	4,897.97	55.98
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,334.00		

INSPECTION

Date of Assignment: 24/10/2017

Date Inspected: 24/10/2017

Estimated Period of Repair: 8.0 days

Inspected At: 3A Automobile Pte Ltd (HQ)
120 Lower Delta Road, #02-15, Cendex Centre
Singapore 169208**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	781.10 F	*781.10 FL
2	2		*REAR BOOT HINGES	Not Necessary	344.90 F	*- FL
3	1		*REAR WEATHERSTRIP	Necessary	182.25 F	*182.25 FL
4	1		*REAR BOOT TOP LOCK	Bent	171.45 F	*171.45 FL
5	1		*REAR BOOT BOTTOM LOCK	Bent	131.35 F	*131.35 FL
6	1		*REAR BOOT TOYOTA LOGO	Necessary	61.10 F	*61.10 FL
7	1		*REAR BOOT WORDING	Necessary	61.35 F	*61.35 FL
8	1		*REAR BUMPER	Deformed	581.45 F	*581.45 FL
9	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	342.90 F	*342.90 FL
10	8		*REAR BUMPER CLIPS	Necessary	103.20 F	*103.20 FL
11	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	357.70 F	*- FL
12	1		*REAR BUMPER FOAM	Cut	181.60 F	*181.60 FL
13	1		*REAR BUMPER REAR END PANEL	Bent	782.10 F	*782.10 FL
14	1		*REAR LHS TAILLAMP ASSY	Not Necessary	374.45 F	*- FL
15	1		*REAR LHS FENDER SHIELD	Not Necessary	182.10 F	*- FL
16	8		*REAR LHS FENDER SHIELD CLIPS	Not Necessary	103.20 F	*- FL
17	1		*REAR PANEL TOP COVERING	Cracked	281.75 F	*281.75 FL
18	1		*SET REAR REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,223.95	3,861.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	915.40
+ Margin on L,N Items 15.00/0.00% (\$\$)	753.59	0.00
Total Parts (\$\$)	5,977.54	2,946.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE THE DAMAGED PARTS AS LISTED ABOVE ,INCLUDING REINSTATEMENTS OF NECESSARY ATTACHMENTS & FITTINGS TO FACILITATE REPAIRS ,JACK,PANEL BEAT & RESHAPE THE AFFECTED PARTS & COMPONENTS ,CORRECT & REALIGN THE NECESSARY PARTS	New	1,200.00	800.00
2	TO PROVIDE SKILL LABOUR & MATERIAL TO DO SURFACE TREATMENT/EPOXY TREATMENT AND TO RESPRAY WITH 2K PAINT ON FRONT RIGHT HAND SIDE DOOR & RIGHT SIDE BOTTOM SIDE SKIRT WITH OVEN SPRAY BOOTH FACILITATE	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,200.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >