

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20012311/ETF3E2-1

Date: 18/05/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00035932000
Claimant Vehicle No : SMG6891P Insured Vehicle No : SCW7888C
Date of Loss: 05/11/2020 Nature of Claim: TP Claim No: SNM20D204238/CO2/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG6891P**
Make & Model: SUZUKI SWIFT, 1.4 1.4 AT SPECIAL EDITION (A) Engine No: K14B1118395
Reg. Date: 23/03/2016 (Man. Year: 2015) Chassis No: JSAFZC82S00323852
Colour: Black Odometer: 89288 km
Engine Capacity: 1372 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R16 Rear Tyre Size: 195/55 R16
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,107.10	621.94	2,485.16	79.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,270.00	2,060.00	61.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,437.10	1,891.94	4,545.16	70.61
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	6,437.10	1,500.00	4,937.10	76.70

INSPECTION

Date of Assignment: 12/11/2020
Date Inspected: 18/11/2020 Inspected At: 8 KAKI BKT AVE 4#08-32
Estimated Period of Repair: 5.0 days Repairer : Benz Bodywork (HQ)

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 May 2021)

Parts: 143 SUZUKI SWIFT 1.4 1.4 AT SPECIAL EDITION (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG6891P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Dented / Distorted	607.20 F	*432.00 FL
2	1		*REAR BUMPER O/S RETAINER	Bent	18.70 F	*18.70 FL
3	1		*REAR O/S BODY PANEL	Repair	387.40 F	*- FL
4	1		*O/S TAILLAMP	Serviceable	264.30 F	*- FL
5	1		*REAR O/S SHOCK ABSORBER	Serviceable	267.00 F	*- FL
6	1		*REAR AXLE CARRIER	Serviceable	1,146.35 F	*- FL
7	1		*REAR O/S WHEEL HUB	Bent	416.15 F	*281.00 FL

F=Franchise part. L=ListItemDisc.

	Sub Total (S\$)	3,107.10	731.70
	- List Item Discount on L Items 0.00/15.00% (S\$)	0.00	109.76
	Total Parts (S\$)	3,107.10	621.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REFIT REAR SEAT, CARPETING & TRIM COVER TO FACILITATE REPAIR	New	300.00	0.00
2	TO DISMANTLE & REPLACE DAMAGED PARTS, TO STRAIGHTEN, REPAIR & RESHAPE REAR O/S BODY PANEL & ALIGN NECESSARY PARTS BACK	New	900.00	400.00
3	TO RENEW REAR UNDECARRIAGE & ALIGN NECESSARY PARTS	New	400.00	50.00
4	TO CHECK & ADJUST WHEEL ALIGNMENT	New	180.00	60.00
5	TO SUPPLY 1 PC REAR O/S ALLOY RIM INCLUDING TRANSFER TYRE & BALANCE TYRE	New	400.00	300.00
6	TO PUTTY & RESPRAY PAINT ON AFFECTED ACCIDENT SECTIONS	New	900.00	400.00
7	TO RESPRAY RUST PROOF ON AFFECTED ACCIDENT AREAS	New	200.00	30.00
8	TO CHECK, TEST LIGHTING FUNCTIONS	New	50.00	30.00
			Gross Labour Cost (\$\$)	1,270.00
			3,330.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >