

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21005620/AVCN2**Date:** 13/10/2021**REFERENCE**

Insured/Claimant: KIM WOOK Policy No:  
Date of Loss: 05/05/2021 Nature of Claim: OD Claim No: 2729036062SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLX8399D**  
Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZ418472  
Reg. Date: 13/04/2018 (Man. Year: 2018) Chassis No: WAUZZZGA1JA063102  
Colour: White Odometer: 29987 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$94,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	29,179.50	17,084.16	12,095.34	41.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,412.00	7,152.00	10,260.00	58.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>46,591.50</b>	<b>24,236.16</b>	<b>22,355.34</b>	<b>47.98</b>
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	46,191.50	23,836.16	22,355.34	48.40
<b>+ GST 7.00/7.00% (S\$)</b>	3,233.41	1,668.53	1,564.88	48.40
<b>Nett Amount (S\$)</b>	<b>49,424.91</b>	<b>25,504.69</b>	<b>23,920.22</b>	<b>48.40</b>

**INSPECTION**

Date of Assignment: 10/05/2021  
Date Inspected: 07/05/2021 Inspected At: 24 BENOI SECTOR  
SINGAPORE 629857  
Estimated Period of Repair: 10.0 days REPAIRER: PREMIUM AUTOMOBILES PTE LTD

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,828.00 FS	*1,547.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	347.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE-CENTER	Cracked	197.00 FS	*157.20 FS
4	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Cut	340.00 FS	*270.40 FS
5	2		*FRONT BUMPER AIR GUIDE GRILLE END CAP-LH/RH	Not Necessary	118.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Deformed	299.00 FS	*238.80 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	156.00 FS	*- FS
8	2		*FRONT WHEEL SPOILER-LH/RH	Not Necessary	68.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTER-LH	Not Necessary	36.00 FS	*- FS
10	1		*FRONT BUMPER ADAPTER-RH	Not Necessary	42.00 FS	*- FS
11	1		*FRONT RADIATOR GRILLE	Cracked	1,411.00 FS	*1,128.80 FS
12	1		*FRONT RADIATOR STRIKER PLATE	Cracked	124.00 FS	*99.20 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	78.00 FS	*61.92 FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	723.00 FS	*578.40 FS
15	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	72.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT COVER	Deformed	100.00 FS	*80.00 FS
17	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
18	1		*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
19	1		*FRONT LOW TONE HORN-LH	Not Necessary	286.00 FS	*- FS
20	1		*FRONT HIGH TONE HORN-RH	Not Necessary	180.00 FS	*- FS
21	2		*FRONT HORN SPRING SHACKLE-LH/RH	Not Necessary	62.00 FS	*- FS
22	2		*FRONT FENDER-LH/RH	Repair	2,294.00 FS	*- FS
23	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	40.00 FS	*- FS
24	2		*FRONT FENDER LONG BRACKET-LH/RH	Not Necessary	96.00 FS	*- FS
25	2		*FRONT FENDER SHORT BRACKET-LH/RH	Not Necessary	32.00 FS	*- FS
26	2		*FRONT FENDER BRACKET	Not Necessary	46.00 FS	*- FS
27	2		*FRONT FENDER BRACKET-LH/RH	Not Necessary	32.00 FS	*- FS
28	2		*FRONT FENDER BRACE-LH/RH	Not Necessary	88.00 FS	*- FS
29	2		*FRONT WHEEL HOUSING LINER-LH/RH	Not Necessary	392.00 FS	*- FS
30	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
31	1		*FRONT BONNET	Dented	2,789.00 FS	*2,231.20 FS
32	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
33	2		*FRONT BONNET LID HINGE-LH/RH	Bent	124.00 FS	*97.76 FS
34	2		*FRONT BONNET STRIKER-LH/RH	Not Necessary	220.00 FS	*- FS
35	1		*FRONT BONNET IMPACT PROTECTION-CENTER/LH/RH (3 Pcs)	Necessary	90.00 FS	*71.20 FS
36	2		*FRONT BONNET COVER	Not Necessary	32.00 FS	*- FS
37	1		*FRONT BONNET PLENUM COVER	Not Necessary	158.00 FS	*- FS
38	2		*FRONT BONNET LID LOCK	Not Necessary	427.00 FS	*- FS
39	1		*FRONT BONNET BOWDEN CABLE-CENTER	Damaged	58.00 FS	*46.00 FS
40	1		*FRONT BONNET COVER	Necessary	10.00 FS	*7.60 FS
41	1		*FRONT BONNET RELEASE ELEMENT	Not Necessary	58.00 FS	*- FS
42	2		*FRONT BONNET BOWDEN CABLE-LH/RH	Damaged	116.00 FS	*92.00 FS
43	1		*FRONT BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
44	2		*HEADLIGHT MOUNTING	Cracked	236.00 FS	*188.80 FS
45	2		*HEADLIGHT-LH/RH	Cracked	9,830.00 FS	*7,864.00 FS
46	2		*HEADLIGHT LIFT CYLINDER-LH/RH	Not Necessary	284.00 FS	*- FS
47	1		*HEADLIGHT HOSE	Cut	182.00 FS	*145.60 FS
48	1		*FRONT RADIATOR LOCK CARRIER	Cracked	994.00 FS	*795.20 FS
49	1		*A/C CONDENSER	Dented	551.00 FS	*440.80 FS
50	1		*COOLANT (6 Pcs)	Necessary	142.00 FS	*113.28 FS
51	1		*FRONT RADIATOR COOLER	Not Necessary	951.00 FS	*- FS
52	1		*FRONT RADIATOR ADDITIONAL COOLER	Not Necessary	859.00 FS	*- FS
53	2		*FRONT RADIATOR AIR GUIDE-LH/RH	Cracked	62.00 FS	*48.32 FS
54	1		*FRONT RADIATOR OUTER SEAL-RH	Not Necessary	7.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*FRONT RADIATOR UPPER AIR GUIDE-CENTRE	Cracked	22.00 FS	*17.20 FS
56	2		*FRONT WHEEL ARCH COVER-LH/RH	Necessary	644.00 FS	*514.40 FS
57	1		*FRONT NUMBER PLATE	Dented	60.00 FS	*60.00 FS
58	1		*SUNDRIES	Necessary	350.00 FS	*57.60 FS
59	1		*WASHER HOSE DISTRIBUTOR (Supplementary)	Necessary	30.00 FS	*23.28 FS
60	2		*WAHSER HOSE ELBOW FITTING (Supplementary)	Necessary	59.00 FS	*46.56 FS
61	1		*AIR INTAKE AIR GUIDE (Supplementary)	Cracked	56.00 FS	*44.48 FS
62	5		*WASHER HOSE CLIP (Supplementary)	Not Necessary	33.50 FS	*- FS
F=Franchise part. S=SpcNett.						
				<b>Total Parts (S\$)</b>	<b>29,179.50</b>	<b>17,084.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO REMOVE & RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR & RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY ON BOTH FRONT DOOR	New	560.00	0.00
5	TO DISMANTLE AND RENEW BOTH FRONT BUMPER,BONNET,BOTH FRONT FENDERS AND BOTH HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,400.00	2,500.00
6	TO RESPRAY FRONT BUMPER,BOTH FRONT FENDER,BONNET,HINGES,BOTH FRONT UPPER-A-PILLARS AND FRONT DOORS	New	7,700.00	2,200.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>17,412.00</b>	<b>7,152.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >