

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005621/T1GS3Q2
Date: 30/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SHA4543Z	Insured Vehicle No :	SGQ6336U
Date of Loss:	06/05/2021	Nature of Claim:	TP
		Claim No:	6049858675SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4543Z	Engine No:	G4LEKU398200
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU186599
Reg. Date:	22/10/2019 (Man. Year: 2019)	Odometer:	195844 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,275.84	298.40	977.44	76.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,025.00	425.00	29.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,725.84	1,323.40	1,402.44	51.45
+ GST 7.00/7.00% (S\$)	190.81	92.64	98.17	51.45

Nett Amount (S\$)	2,916.65	1,416.04	1,500.61	51.45
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,124.29		

INSPECTION

Date of Assignment: 07/05/2021

Date Inspected: 07/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER COVER	Repair	418.30 FL	*- FL
2	10		*FRT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*FRT BUMPER BRACKET RH	Not Necessary	28.00 FL	*- FL
4	1		*FRT FENDER RH	Repair	588.80 FL	*- FL
5	1		*FRT FENDER SHIELD RH	Not Necessary	164.70 FL	*- FL
6	1		*FRT FENDER EMBLEM BLUR DRIVE RH	Necessary	26.60 FL	*26.60 FL
7	1		*FRT WHEEL HUB CAP RH	Cut	346.40 FL	*346.40 FL
					Sub Total (\$\$)	1,594.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	318.96
					Total Parts (\$\$)	1,275.84

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	525.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	TUFF KOTE	New	50.00	0.00
Gross Labour Cost (\$\$)			1,450.00	1,025.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >