

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI21003468/GVF3E2-1

Date: 08/06/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00063452004		
Claimant Vehicle No :	SMX3939S	Insured Vehicle No :	SGV4161T		
Date of Loss:	13/03/2021	Nature of Claim:	TP	Claim No:	SNM21D201459/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX3939S	Engine No:	27186030030032
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Chassis No:	WDD2120472A155929
Reg. Date:	12/07/2010 (Man. Year: 2009)	Odometer:	112776 km
Colour:	Silver		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,744.00	7,424.40	9,319.60	55.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	2,120.00	2,280.00	51.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,144.00	9,544.40	11,599.60	54.86
Approved Total (Overridden) (\$\$)		7,600.00		
(\$\$)	21,144.00	7,600.00	13,544.00	64.06
+ GST 7.00/7.00% (\$\$)	1,480.08	532.00	948.08	64.06
Nett Amount (\$\$)	22,624.08	8,132.00	14,492.08	64.06

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 25/05/2021 Inspected At:

Estimated Period of Repair: 7.0 days

Bluwel Automotive Service Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
Autobay@Kaki Bukit
Singapore 417883

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2021)
Parts:	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX3939S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repaired	2,850.00 F	*- FN
2	1		*BOOT LID INNER LOCK	Replaced	320.00 F	*320.00 FN
3	1		*BOOT LID LOCK CATCH	Serviceable	65.00 F	*- FN
4	1		*BOOT LID LOGO	Replaced	78.00 F	*78.00 FN
5	1		*BOOT LID E250 EMBLEM	Replaced	85.00 F	*85.00 FN
6	1		*BOOT LID CGI EMBLEM	Replaced	68.00 F	*68.00 FN
7	1		*BOOT LID CLOSURE MOTOR	Serviceable	454.00 F	*- FN
8	2		*REAR TAILLAMPS	Replaced	1,440.00 F	*1,440.00 FN
9	1		*REAR END PANEL	Replaced	1,048.00 F	*1,048.00 FN
10	1		*REAR END PANEL INNER GARNISH	Replaced	152.00 F	*152.00 FN
11	1		*REAR BUMPER	Replaced	1,680.00 F	*1,680.00 FN
12	1		*REAR BUMPER LOWER	Replaced	395.00 F	*395.00 FN
13	2		*REAR BUMPER SIDE BRACKETS	Replaced	90.00 F	*90.00 FN
14	1		*REAR BUMPER CENTRE BRACKET	Replaced	114.00 F	*114.00 FN
15	1		*REAR BUMPER REINFORCEMENT	Replaced	850.00 F	*850.00 FN
16	2		*REAR BUMPER SIDE RETAINERS	Replaced	96.00 F	*96.00 FN
17	1		*REAR BUMPER CENTRE CHROME MOULDING	Replaced	190.00 F	*190.00 FN
18	2		*REAR BUMPER SIDE CHROME MOULDINGS	Replaced	280.00 F	*280.00 FN
19	1		*REAR BUMPER TOW HOOK COVER	Replaced	28.00 F	*28.00 FN
20	1		*REAR BUMPER REVERSE SENSORS (4PCS)	Replaced (3Pcs Only)	1,144.00 F	*585.00 FN
21	1		*REAR SPARE TYRE PANEL (FIBER)	Replaced	275.00 F	*275.00 FN
22	1		*REAR SPARE TYRE PANEL	Repaired	1,065.00 F	*- FN
23	1		*REAR SPARE TYRE SIDE UNDERCOVER	Replaced	142.00 F	*142.00 FN
24	1		*REAR EXHAUST SILENCER	Repaired	1,835.00 F	*- FN
25	2		*REAR EXHAUST SILENCER MOUNTINGS	Serviceable	140.00 F	*- FN
26	2		*FRONT SEAT HEADRESTS (LOCAL REPAIR)	Replaced	1,860.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	16,744.00	8,216.00
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	791.60
Total Parts (\$\$)	16,744.00	7,424.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	New	50.00	40.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS	New	100.00	80.00
3	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS	New	150.00	100.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,900.00	1,000.00
5	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	150.00	60.00
6	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	150.00	40.00
7	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,900.00	800.00
Gross Labour Cost (S\$)			4,400.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >