

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN		Ref:	CS3/LPC21005639/R1tf3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	20/05/2021	
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YP 486B	Veh. Inspected		GBH 6383P
	Policy No.		Coverage (\$)		0.00
	Claim No.	20/21/21/VC05/024535	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		10/05/2021
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA 150 5MT	c.c		2982
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	JTFAT35Y60K211159	Colour		BLUE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15C	HABILEAD		7 mm
	L/H Front Tyre	195 R15C	HABILEAD		7 mm
	R/H Rear Tyre	155 R12C (D)	HABILEAD		6/6 mm
	L/H Rear Tyre	155 R12C (D)	HABILEAD		6/6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT O/S PORTION.			
5.	General Information				
	Accident Date	04/05/2021	Inspect Date /	Time	10/05/2021 (02:42 PM)
	Survey held at	GOLD AUTOWORKS PTE LTD			
		48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21005639/R1tf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser