

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21005643/Uvce2	
	8 SHENTON WAY TOWERSINGAPOR	-		Date:	27/05/2021	
	ATTN: NG STACE	Y		Code:	ASM	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 8068C	Veh. Inspected		SLS 269A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M039RK	Excess (\$)		0.00	
	Assign From	NG STACEY	Assign Date		10/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3 (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6BN22A8H0167403	Colour		GREY	
	Odometer	92402 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	CONTINENTAL		6 mm	
	L/H Front Tyre	205/60 R16	CONTINENTAL		6 mm	
	R/H Rear Tyre	205/60 R16	CONTINENTAL		6 mm	
	L/H Rear Tyre	205/60 R16	CONTINENTAL		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
5.	General Information					
	Accident Date	08/05/2021	Inspect Date / 1	Time	11/05/2021 (11:00 AM)	
	Survey held at	Survey held at 25 Kaki Bukit Road 4 #07-38 Synergy				
	Repairer	Repairer TRIPLE-T AUTOMOBILE				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days					

Report Ref No. CS3/ASM21005643/Uvce2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$