

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref: CS/SMO21005644/Ktf3n2	
50 RAFFLES PLACE #03-03			Date: 01/06/2021	
SINGAPORE LAND TOWERSINGAPORE 048623			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBQ 7190A	Veh. Inspected	CB 6682X	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101455/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	10/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JTFST22P600009878	Colour	MULTI COLOUR	
Odometer	316539 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	6 mm	
L/H Front Tyre	195 R15X8	MICHELIN	6 mm	
R/H Rear Tyre	195 R15X8	MICHELIN	5 mm	
L/H Rear Tyre	195 R15X8	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2021	Inspection Date	11/05/2021	
Survey held at	A T AUTO CONSULTANT 113 TECK WHYE LANE, #05-650, SINGAPORE 680113			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	