



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 6682X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DENTED / CRACKED	890.00	523.30
1	FRONT BUMPER BRACKET LH	SERVICEABLE	179.00	-
1	HEADLAMP RH	CUT	950.00	848.70
1	FRONT CORNER PANEL LH	TO REPAIR SEE LABOUR	267.00	-
1	SIDE MIRROR LH	SERVICEABLE	389.00	-
	LESS 25% DISCOUNT		-668.75	-343.00
			2,006.25	1,029.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL LH.		500.00	250.00
	SPRAY PAINTING ON ACCIDENT AREAS.		500.00	280.00
	WIRING CHARGES.		100.00	20.00
	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS.	NOT NECESSARY	150.00	-
			1,250.00	550.00
<b>GRAND TOTAL</b>			<b>3,256.25</b>	<b>1,579.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,250.00</b>

Report Ref No. CS/SMO21005644/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.