



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005644/Ktf3n2	
			Date: 01/06/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	FBQ 7190A	Veh. Inspected	CB 6682X
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101455/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	10/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE (A)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	JTFST22P600009878	Colour	MULTI COLOUR
	Odometer	316539 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	MICHELIN	6 mm
	L/H Front Tyre	195 R15X8	MICHELIN	6 mm
	R/H Rear Tyre	195 R15X8	MICHELIN	5 mm
	L/H Rear Tyre	195 R15X8	MICHELIN	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	07/05/2021	Inspection Date	11/05/2021
	Survey held at	A T AUTO CONSULTANT 113 TECK WHYE LANE, #05-650, SINGAPORE 680113		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	