

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005652/ERA3Q2
Date: 26/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMT8548A	Insured Vehicle No :	SMF5872G
Date of Loss:	07/05/2021	Nature of Claim:	TP
		Claim No:	0605244460SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT8548A		
Make & Model:	KIA CERATO, 1.6 EX (A)	Engine No:	G4FGKH755795
Reg. Date:	21/07/2020 (Man. Year: 2019)	Chassis No:	KNAF3416ML5069606
Colour:	Blue	Odometer:	16479 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,431.80	1,700.00	2,731.80	61.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	2,160.00	1,670.00	43.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,261.80	3,860.00	4,401.80	53.28
+ GST 7.00/7.00% (S\$)	578.33	270.20	308.13	53.28

Nett Amount (S\$)	8,840.13	4,130.20	4,709.93	53.28
+ Car Rental (6.0 x S\$80.00/day + 7.00% GST) (S\$)		513.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,645.80		

INSPECTION

Date of Assignment: 10/05/2021

Date Inspected: 02/06/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

209 Pandan Gardens

Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*W/STRIP -TRUNK LID OPNG	Not Necessary	80.00 FS	*- FS
4	1		*LATCH ASSY -TRUNK LID	Not Necessary	89.60 FS	*- FS
5	1		*STRIKER ASSY -TRUNK LID	Not Necessary	32.00 FS	*- FS
6	1		*PANEL ASSY -TRUNK LID	Dented	1,037.60 FS	*1,037.60 FS
7	1		*EMBLEM -CERATO	Necessary	22.40 FS	*22.40 FS
8	1		*ORNAMENT-KIA NO.115	Necessary	25.60 FS	*25.60 FS
9	1		*COVER -RR BUMPER	Dented	520.80 FS	*520.80 FS
10	1		*COVER -RR BUMPER LWR	Not Necessary	192.80 FS	*- FS
11	1		*COVER -RR BUMPER FOG LAMP, RH	Cut	15.20 FS	*15.20 FS
12	1		*LAMP ASSY -SIDE T/SIGNAL RH	Not Necessary	144.80 FS	*- FS
13	1		*BEAM -RR BUMPER	Not Necessary	254.40 FS	*- FS
14	2		*GROMMET ASSY -SCREW	Necessary	3.20 FS	*3.20 FS
15	7		*CLIP	Necessary	5.60 FS	*5.60 FS
16	1		*STAY- RR BUMPER LH	Not Necessary	52.00 FS	*- FS
17	1		*STAY- RR BUMPER RH	Not Necessary	52.00 FS	*- FS
18	1		*BRACKET -RR BEAM UPR MTG ,LH	Not Necessary	7.20 FS	*- FS
19	1		*BRACKET -RR BEAM UPR MTG ,RH	Not Necessary	7.20 FS	*- FS
20	1		*BRACKET -RR BEAM LWR ,CTR	Not Necessary	4.80 FS	*- FS
21	2		*BRACKET -RR BEAM LWR MTG	Broken	9.60 FS	*9.60 FS
22	8		*RETAINER -BUMPER SIDE MTG	Not Necessary	19.20 FS	*- FS
23	1		*BRACKET ASSY -RR BPR SIDE UPR ,L	Not Necessary	20.00 FS	*- FS
24	1		*BRACKET ASSY -RR BPR SIDE UPR ,R	Not Necessary	24.80 FS	*- FS
25	1		*NEW K3 2020 GRAVITY BLUE BAU	Repair	1,721.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	4,431.80
						1,700.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER ,REAR BOOT AND AFFECTED AREAS REPAIR REAR END PANEL	New	2,000.00	800.00
2	SPRAY ON REAR BUMPER ,BOOT ,RR BUMPER BODY KIT & END PANEL	New	1,400.00	1,050.00
3	REMOVE AND INSTALL REAR PARKING ASSIST	New	120.00	80.00
4	REMOVE AND INSTALL REAR BODYKIT FOR FACILITATE REPAIR	New	80.00	80.00
5	TO PERFORM RUST PREVENTION	New	80.00	0.00
6	CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (S\$)			3,830.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >