



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Mccarl Leonardo
C/o: 160 Sin Ming Drive #06-10
Sin Ming AutoCity (S) 575722

Date of report: 27.02.2021
Date of request: 02.02.2021
Date of inspection: 02.02.2021
Date of accident: 29.01.2021
Claim type: Third Party Claim

Report No: AAS/2021/036

Particulars of affected vehicle:

Registration no: SMH1944Z
Make/Model: Mazda 6 (A)
Year of registration: 2019/19
Colour: Metallic Grey

Odometer: 27246 km
Engine Capacity: 1998 cc
Engine no: PE21254670
Chassis no: JM6GL1072K0311710

Condition of tires:

Front Left: 6mm
Make: Bridgestone
Rear Left: 6mm
Make: Bridgestone

Front Right: 6mm
Make: Bridgestone
Rear Right: 6mm
Make: Bridgestone

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conduct at M/s. Lian Heng Painter Company
160 Sin Ming Drive #06-10
Sin Ming AutoCity (S) 575722

(Subsequent Inspection was conducted)

Assessment

Repairer's estimate:	\$ 6,666.72
Revised estimate:	\$ 5,909.12
Recommended reserve:	\$ 4,750.00 (Lump sum)

Estimated normal duration of repairs : 6 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0418 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SMH1944Z

Report No: AAS/2021/036

W/O PREJUDICE

Point of impact

At the rear portion. The LHR was also affected.

General description of damages

The rear bumper, rear end panel, LH tail lamp, LHR fender, LHR door, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Lian Heng Painter Company as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$5,909.12

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$4,750.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 6 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 77 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0418 Fax: 6266-7596
Email: absolute.app.svcs@gmail.com

Vehicle No: SMH1944Z

Report No: AAS/2021/036

Appraisement Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Rear bumper / CR4	1	Dented/Broken		\$ 1,266.60	\$ 1,266.60 ✓
2	Rear bumper reflector LH/RH XMC	2	Refit	\$ 53.00	\$ 106.00	-
3	Rear bumper tow hook cover / CR4	2	Missing	\$ 15.90	\$ 31.80	\$ 31.80 ✓
4	Rear bumper parking sensor / short	2	Malfunctioned	\$ 193.90	\$ 387.80	\$ 387.80 ✓
5	Rear bumper retainer LH/RH / CRA	2	LH Cracked	\$ 41.00	\$ 82.00	\$ 41.00 ✓
6	Rear bumper reinforcement / BT	1	Dented		\$ 583.30	\$ 583.30 ✓
7	Rear bumper support / BR	1	Cracked		\$ 90.60	\$ 90.60 ✓
8	Rear bumper clips / NRC	8	Necessary	\$ 3.30	\$ 26.40	\$ 26.40 ✓
9	Tail lamp LH / CR4	1	Broken		\$ 762.80	\$ 762.80 ✓
10	Radar module LH XSV	1	Dented/Cracked		\$ 1,625.20	\$ 1,625.20 X
11	Radar module bracket LH / CRA	1	Dented/Cracked		\$ 83.40	\$ 83.40 ✓
12	Rear end panel XN		Dented/Repair		-	-
13	LHR fender XN		Dented/Repair		-	-
14	LHR door XR		Grazed/Repair		-	-
						3,273.70
Total:					\$ 5,045.90	\$ 4,898.90
-20%					\$ 1,009.18	\$ 979.78
List total:					\$ 4,036.72	\$ 3,919.12

S/N	Labour Description	Repairer's Est	Revised Est
1	To check rear wirings.	\$ 50.00	\$ 30.00 ✓
2	To remove & refit rear seat, rear luggage trimmings, etc.	\$ 100.00	\$ 60.00 X
3	To renew & transfer reverse sensors.	\$ 80.00	\$ 50.00 ✓
4	To conduct/check wheel alignment.	\$ 80.00	\$ 60.00 X
5	Rust proofing on rear affected panels..	\$ 120.00	\$ 90.00 50
6	To remove and renew rear damaged parts. Re-align all affected area.	\$ 1,000.00	\$ 750.00 400
7	To putty and respray all rear damaged parts. Touch up all affected area.	\$ 1,200.00	\$ 950.00 650

Labour Total: \$ 2,630.00 \$ 1,990.00

Grand Total: \$ 6,666.72 \$ 5,909.12

The final adjusted lump sum amount is \$4,750.00

Under normal circumstances, the repair should be completed within a reasonable period of 6 working days.

77 Photographs were taken at the time of inspection.

3,273.70
- 20%
2,618.96
1,180
3,798.96
- 20%
3,034.17

L/S
\$ 3,050.
3 days

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.