

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21005663/UGS3Q2

Date:

18/08/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MPC0001821

Claimant Vehicle No : SKW4614B**Insured Vehicle No :**

SML2275T

Date of Loss: 07/05/2021

Nature of Claim:

TP

Claim No:

MPC2021D0002091

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKW4614B**

Make & Model: NISSAN QASHQAI, 1.2 (A)

Engine No:

HRA2185454A

Reg. Date: 30/10/2015 (Man. Year: 2015)

Chassis No:

SJNFEAJ11U1475776

Colour: White

Odometer:

79979 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side: Pace 8 mm

Rear Left Side:

Pace 8 mm

Front Right Side: Pace 8 mm

Rear Right Side:

Pace 8 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,408.38	2,000.12	3,408.26	63.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,520.00	1,220.00	44.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,148.38	3,520.12	4,628.26	56.80
Approved Total (Overridden) (S\$)		2,800.00		

Nett Amount (S\$)	8,148.38	2,800.00	5,348.38	65.64
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,307.45		

INSPECTION

Date of Assignment: 10/05/2021

Date Inspected: 11/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Black Eagle Auto Pte Ltd (HQ)
 25 KAKI BUKIT ROAD 4, #05-80
 Singapore 417800

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2021)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW4614B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (COMPLETE)	Distorted	1,452.00 FL	*717.00 FL
2	1		*REAR BUMPER TOWING COVER	Cut	115.20 FL	*22.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	692.00 FL	*619.20 FL
4	1		*REAR END PANEL	Bent	982.00 FL	*482.60 FL
5	1		*REAR SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	98.00 FN	*- FN
7	2		*REAR BUMPER REFLECTORS	Not Necessary	153.60 FN	*- FN
8	1		*REAR END PANEL TOP GARNISH	Not Necessary	198.00 FN	*- FN
9	1		*REAR EXHAUST SILENCER ASSEMBLY	Not Necessary	1,285.00 FN	*- FN
10	4		*REAR EXHAUST SILENCER ASSEMBLY MOUNTINGS	Not Necessary	50.00 FN	*- FN
11	1		*REAR BUMPER ENERGY ABSORBER FOAM	Torn	126.00 FN	*126.00 FN
12	1		*REAR BUMPER LOWER DIFFUSER (CHROME)	Not fitted	980.00 FS	*- FS
13	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
14	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
15	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	6,571.80	2,196.80
- List Item Discount on L Items 30.00/10.00% (\$\$)	972.36	184.08
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	191.06	12.60
Total Parts (\$\$)	5,408.38	2,000.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE DAMAGED PARTS AND COMPONENTS	New	1,200.00	600.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	900.00	780.00
3	TO REMOVE AND REFIX REAR INNER TRIMS ,GARNISH & AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR PORTION	New	150.00	60.00
4	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSEMBLY REALIGN TO FIT AND CHECK FOR PROPER SYSTEM FUNCTION	New	250.00	0.00
5	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	120.00	50.00
6	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	120.00	30.00
Gross Labour Cost (\$\$)			2,740.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >