

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005667/AGS3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SGW853B**Insured Vehicle No :** GBG2615C

Date of Loss: 06/05/2021

Nature of Claim: TP

Claim No: 7949968131SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGW853B**

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX559301

Reg. Date: 04/07/2007 (Man. Year: 2007)

Chassis No: MR053HY9305005575

Colour: Black

Odometer: 261621 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R16

Rear Tyre Size: 205/45 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,792.62	6,021.90	2,770.72	31.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,840.00	2,830.00	3,010.00	51.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,632.62	8,851.90	5,780.72	39.51
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	14,632.62	7,000.00	7,632.62	52.16
+ GST 7.00/7.00% (S\$)	1,024.28	490.00	534.28	52.16
Nett Amount (S\$)	15,656.90	7,490.00	8,166.90	52.16
+ Loss of Use (13.0 x S\$50.00/day) (S\$)		650.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		8,147.49		
Global Sum Settlement (S\$)		8,100.00		

INSPECTION

Date of Assignment: 07/05/2021

Date Inspected: 07/05/2021 Inspected At:

Kang Car Repairers Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki

Bukit

Singapore 417883

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Distorted	658.70 FL	*658.70 FL
2	1		*BOOT LID LOGO	Necessary	51.10 FL	*51.10 FL
3	1		*BOOT LID VIOS EMBLEM	Necessary	46.20 FL	*46.20 FL
4	1		*REAR NUMBER PLATE GARNISH	Deformed	129.80 FL	*129.80 FL
5	2		*REAR NUMBER PLATE LAMP	Not Necessary	130.40 FL	*- FL
6	1		*BOOT LID KEY LOCK	Not Necessary	98.80 FL	*- FL
7	1		*BOOT LID INNER LOCK	Damaged	195.90 FL	*195.90 FL
8	1		*BOOT LID INNER LOCK CHECKER	Not Necessary	28.40 FL	*- FL
9	1		*BOOT LID INNER LOCK CABLE	Not Necessary	68.50 FL	*- FL
10	1		*BOOT LID RUBBER	Cut	175.30 FL	*175.30 FL
11	1		*REAR PANEL	Dented	620.10 FL	*620.10 FL
12	1		*REAR PANEL TRIM	Deformed	232.00 FL	*232.00 FL
13	1		*REAR FENDER TRIM RH	Not Necessary	355.90 FL	*- FL
14	1		*REAR FENDER TRIM LH	Not Necessary	355.90 FL	*- FL
15	1		*TAIL LAMP-RH	Cracked	357.20 FL	*357.20 FL
16	1		*TAIL LAMP PANEL RH	Repair	168.90 FL	*- FL
17	1		*TAIL LAMP -LH	Cracked	357.20 FL	*357.20 FL
18	1		*TAIL LAMP PANEL LH	Repair	168.90 FL	*- FL
19	1		*SPARE TYRE PANEL	Repair	637.80 FL	*- FL
20	1		*SPARE TYRE PANEL COVER	Torn	114.90 FL	*114.90 FL
21	1		*REAR SPARE TYRE PANEL RH SPONGE	Deformed	214.10 FL	*214.10 FL
22	1		*SPARE TYRE PANEL LH SPONGE	Deformed	214.10 FL	*214.10 FL
23	1		*REAR BUMPER	Distorted	467.50 FL	*467.50 FL
24	2		*REAR BUMPER BRACKET	Not Necessary	127.60 FL	*- FL
25	2		*REAR BUMPER SIDE RETAINER	Necessary	184.60 FL	*184.60 FL
26	2		*REAR BUMPER SMALL RETAINER	Not Necessary	64.40 FL	*- FL
27	1		*REAR BUMPER MUDFLAP LH	Not Necessary	65.90 FL	*- FL
28	1		*REAR BUMPER REFLECTOR -LH	Missing	82.80 FL	*82.80 FL
29	1		*FRT BUMPER	Deformed	427.30 FL	*427.30 FL
30	1		*FRT BUMPER REINFORCEMENT	Bent	372.10 FL	*372.10 FL
31	1		*FRT BUMPER BRACKET	N/S Bent	342.80 FL	*171.60 FL
32	2		*FRT BUMPER SIDE RETAINER	Necessary	64.80 FL	*64.80 FL
33	1		*FRT BUMPER TOP BRACKET	Deformed	128.50 FL	*128.50 FL
34	1		*FRT BUMPER GRILLE	Not Necessary	94.80 FL	*- FL
35	1		*FRT SUPPORT PANEL	Repair	756.90 FL	*- FL
36	1		*FRT GRILLE	Cracked	223.80 FL	*223.80 FL
37	1		*FRT GRILLE CHROME	Damaged	106.70 FL	*106.70 FL
38	1		*HEADLAMP LH	Cracked	525.30 FL	*525.30 FL
39	1		*HEADLAMP RH	Cracked	525.30 FL	*525.30 FL
40	1		*AIRCON CONDENSER	Dented	982.30 FL	*982.30 FL
41	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
42	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS
43	1		*SET REAR FENDER TRIM CLIPS RH	Not Necessary	50.00 FS	*- FS
44	1		*SET REAR FENDER TRIM CLIPS LH	Not Necessary	50.00 FS	*- FS
45	1		*SET REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
46	1		*SET FRT BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
47	1		*SET FRT BUMPER GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
48	1		*FRT NUMBER PLATE	Bent	50.00 FS	*30.00 FS
49	1		*FRT GRILLE EMBLEM	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,523.50	7,929.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,730.88	1,907.30
Total Parts (\$\$)	8,792.62	6,021.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
3	TO REMOVE AND REFIT INNER BOOT TRIM	New	120.00	60.00
4	TO SPRAY UNDERSEAL	New	120.00	60.00
5	(REAR) TO SPRAY PAINTING	New	1,400.00	1,000.00
6	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,400.00	800.00
7	TO CHECK WIRING	New	50.00	30.00
8	TO REFILL AIRCON GAS	New	120.00	0.00
9	TO SPRAY UNDERSEAL	New	100.00	0.00
10	(FRONT) TO SPRAY PAINTING	New	1,200.00	400.00
11	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS	New	1,200.00	400.00
Gross Labour Cost (\$\$)			5,840.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >