

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21005673/NRA3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700055899
<b>Claimant Vehicle No :</b>	SHA88Y	<b>Insured Vehicle No :</b>	SJK885L
Date of Loss:	07/05/2021	Nature of Claim:	TP
		Claim No:	1516782184SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA88Y</b>	Engine No:	G4LEKU376317
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU180534
Reg. Date:	22/10/2019 (Man. Year: 2019)	Odometer:	183786 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	Davanti 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	Davanti 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,818.20	1,198.28	619.92	34.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,230.00	300.00	19.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,348.20</b>	<b>2,428.28</b>	<b>919.92</b>	<b>27.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	234.37	169.98	64.39	27.47
<b>Nett Amount (S\$)</b>	<b>3,582.57</b>	<b>2,598.26</b>	<b>984.31</b>	<b>27.47</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$128.40/day) (S\$)</b>		513.60		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,313.86</b>		

INSPECTION

Date of Assignment:	10/05/2021	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	10/05/2021	Inspected At: 59 Loyang Drive
Estimated Period of Repair:	3.0 days	Singapore 508969

**Adjuster:** Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Cracked	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Serviceable	138.10 FL	*- FL
6	1		*REAR BUMPER FOG LAMP	Serviceable	201.50 FL	*- FL
7	1		*LICENCE LAMP	Not Working	85.30 FL	*85.30 FL
8	1		*ANTENNA ASSY -SMARTK	Serviceable	40.50 FL	*- FL
9	1		*BOOTLID HYUNDAI PLATE	Necessary	24.30 FL	*24.30 FL
10	1		*EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
11	1		*EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
12	1		*BOOTLID COMFORT TEL NO STICKER	Necessary	35.00 FS	*35.00 FS
13	1		*BOOTLID COMFORT LOGO STICKER	Necessary	30.00 FS	*30.00 FS
14	1		*REAR NUMBER PLATE + TRIM COVER	Cracked	45.00 FS	*45.00 FS
15	1		*BOOTLID COMFORT APP STICKER	Necessary	30.00 FS	*30.00 FS
16	1		*REAR BUMPER REVERSE SENSOR	Deformed	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,192.75	1,417.85
- List Item Discount on L Items 20.00/20.00% (S\$)	374.55	219.57
Total Parts (S\$)	1,818.20	1,198.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,530.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >