

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005676/APS3Q2
Date: 13/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100499205-04
Claimant Vehicle No :	SLJ7946E	Insured Vehicle No :	SLK6643E
Date of Loss:	04/05/2021	Nature of Claim:	TP
		Claim No:	8249737285SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ7946E		
Make & Model:	HONDA JAZZ, 1.3 HYBRID (A)	Engine No:	L15B31190705
Reg. Date:	27/12/2016 (Man. Year: 2016)	Chassis No:	JHMGK5850HX201018
Colour:	Bronze	Odometer:	81580 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,508.64	1,990.00	1,518.64	43.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,530.00	2,070.00	57.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,108.64	3,520.00	3,588.64	50.48
Approved Total (Overridden) (S\$)		2,800.00		

Nett Amount (S\$)	7,108.64	2,800.00	4,308.64	60.61
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 06/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Hua Meng Spray Painting Workshop (HQ)
 No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	740.00 FL	*558.00 FL
2	1		*REAR BUMPER SIDE HOLDER	O/S Damaged	72.00 FL	*36.00 FL
3	1		*REAR BUMPER LOWER SIDE GARNISH	O/S Cut	108.00 FL	*54.00 FL
4	1		*REAR LAMP	Cut	336.00 FL	*336.00 FL
5	1		*REAR RH FENDER	Distorted	855.80 FL	*855.80 FL
6	1		*REAR RH FENDER INNER TRIM	Deformed	253.50 FL	*253.50 FL
7	1		*REAR RH FENDER INNER SHIELD	Torn	240.00 FL	*83.70 FL
8	1		*REAR RH FENDER LOWER GARNISH	Not Necessary	127.50 FL	*- FL
9	1		*REAR RH FENDER LOWER AIRVENT	Deformed	48.00 FL	*48.00 FL
10	1		*REAR EXHAUST PIPE	Not Necessary	630.00 FL	*- FL
11	4		*REAR BUMPER REVERSE SENSOR	Damaged (1 PCS ONLY)	720.00 FS	*180.00 FS
12	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,190.80	2,435.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	682.16	445.00
Total Parts (\$\$)	3,508.64	1,990.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	0.00
2	REMOVE & REINSTALL QUARTER GLASS	New	100.00	60.00
3	REMOVE & REINSTALL UPHOLSTERY	New	150.00	60.00
4	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
5	REMOVE & REINSTALL EXHAUST PIPE	New	100.00	0.00
6	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,500.00	700.00
7	RESPRAY PAINTING	New	1,300.00	600.00
8	TUFF KOTE	New	100.00	60.00
Gross Labour Cost (S\$)			3,600.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >