

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21005677/EVF3E2

Date: 04/06/2021

REFERENCE

Insured/Claimant:	TAN LAY CHEO	Policy No:	1800117426		
Date of Loss:	08/05/2021	Nature of Claim:	OD	Claim No:	2641497545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME5919L		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UHH5805
Reg. Date:	08/10/2018 (Man. Year: 2018)	Chassis No:	MMBSTA13AJH003683
Colour:	Red	Odometer:	60331 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,889.67	4,506.09	1,383.58	23.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,030.00	2,715.00	3,315.00	54.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,919.67	7,221.09	4,698.58	39.42
+ GST 7.00/7.00% (S\$)	834.38	505.48	328.90	39.42
Nett Amount (S\$)	12,754.05	7,726.57	5,027.48	39.42

INSPECTION

Date of Assignment: 10/05/2021

Date Inspected: 10/05/2021 Inspected At:

Estimated Period of Repair: 7.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
2	1		*BODY PNL SEALANT	Not Necessary	60.00 FS	*- FS
3	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
4	1		*FACE, FR BUMPER	Broken	706.00 FL	*706.00 FL
5	1		*COVER, FR BUMPER	Crushed	13.00 FL	*13.00 FL
6	1		*GRILLE, FR UNDER	Broken	165.00 FL	*165.00 FL
7	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
8	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
9	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
10	5		*CLIP, FR BUMPER	Necessary	20.00 FL	*20.00 FL
11	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
12	1		*GRILLE, RADIATOR	Broken	557.00 FL	*557.00 FL
13	1		*FENDER, FR RH	Dented	500.00 FL	*500.00 FL
14	1		*SHIELD, FR WHEELHOUSE, RH	Torn	98.00 FL	*98.00 FL
15	6		*CLIP, INNERSHIELD	Necessary	24.00 FL	*24.00 FL
16	1		*PANEL ASSY, FR END	Bent	1,055.00 FL	*1,055.00 FL
17	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	99.00 FL	*- FL
18	1		*PANEL, AIR GUIDE, RH	Broken	11.00 FL	*11.00 FL
19	1		*HEADLAMP ASSY, RH	Broken	663.00 FL	*663.00 FL
20	1		*LAMP ASSY, FOG, FR LH	Not Necessary	305.00 FL	*- FL
21	1		*TANK, WINDSHIELD WASHER	Crushed	75.00 FL	*75.00 FL
22	1		*PANEL, AIR GUIDE	Not Necessary	112.00 FL	*- FL
23	1		*RADIATOR ASSY	Not Necessary	972.00 FL	*- FL
24	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
25	1		*UNPAINTED BODYKITS	Broken	1,643.00 FN	*1,643.00 FN
26	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
27	1		*GARNISH, FR BUMPER, RH	Cut	127.00 FL	*127.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	7,541.00	5,777.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,322.73	942.31
- Nett Item Discount on N Items 20.00/20.00% (S\$)	328.60	328.60
Total Parts (S\$)	5,889.67	4,506.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BODY KIT, RHF FENDER & SUPPORT PNL. REPAIR RHF DOOR & BONNET	New	2,760.00	675.00
2	RESPRAY FRT BUMPER, FRT BUMPER BODY KIT, FRT SUPPORT, RHF FENDER, RHF DOOR & BONNET	New	2,100.00	1,050.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AIRCON GAS	New	80.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
8	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
9	SPRAY PAINT FRONT SUPPORT PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$)			6,030.00	2,715.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >